

. .& .

3

()

μ

2

μ

2012

111	15.643441
112	17.205541
113	20.290479
114	23.647167
115	21.561131
116	20.290479
117	16.609513
118	10.001019
211	1.271500
212	1.539700
213	1.949500
214	4.550000
215	1.118700
221	.099900
222	.116200
223	.119300
224	.070000
231	.927000
232	2.184000
233	.559100
234	.857700
235	.622500
236	.622500
237	1.218000
238	.559100
239	8.300000
241	7.750000
242	4.500000
243	2.400000
244	2.700000
251	290.000000
252	290.000000
261	15.100000
262	26.300000
263	32.400000
264	64.100000
265	115.100000
271	206.300000
281	21.300000
282	30.000000
283	36.300000
284	75.400000
301	3.860000
302	6.360000
321	.594700
323	.580000
324	.580000
325	2.780000
326	1.310000
327	.540000
328	1.840000
329	.730000
351	775.000000
352	1,045.000000
353	3.630000
354	4.020000
355	.121800
401	268.420000
402	380.180000

403	103.360000
404	212.730000
405	206.720000
406	320.980000
407	55.210000
408	4.530000
409	126.080000
410	116.530000
411	27.370000
412	2.990000
413	4.530000
414	6.250000
415	8.780000
416	13.540000
417	134.530000
418	44.890000
419	4.530000
420	97.290000
421	32.560000
422	38.010000
423	12.540000
424	41.920000
425	165.330000
426	1,234.850000
427	185.840000
428	437.840000
429	77.590000
501.1M	287.610000
501.2M	322.830000
501.3M	281.740000
501.4M	199.570000
502.1M	326.260000
502.2M	478.520000
502.3M	677.380000
502.4M	901.110000
502.5M	1,590.920000
502.6M	664.960000
504.1M	297.020000
504.2M	436.790000
504.3M	220.140000
504.4M	269.060000
505.1M	639.700000
505.2M	762.190000
506.10M	383.030000
506.1M	123.390000
506.2M	134.110000
506.3M	174.620000
506.4M	199.400000
506.5M	177.030000
506.6M	209.220000
506.7M	413.070000
506.8M	247.840000
506.9M	297.410000
508.1M	18.310000
508.2M	21.970000
508.3M	31.740000
508.4M	42.730000
509.1M	92.080000
509.2M	92.080000

509.3M	96.230000
509.4M	99.910000
511.1M	11.180000
511.2M	11.180000
511.3M	14.900000
511.4M	14.900000
511.5M	16.890000
511.6M	15.650000
512.1M	1.530000
512.2M	1.980000
512.3M	1.980000
512.4M	2.590000
512.5M	2.590000
512.6M	4.420000
512.7M	4.420000
512.8M	15.260000
512.9M	21.360000
514.1M	243.560000
514.2M	249.800000
514.3M	319.750000
514.4M	337.230000
514.5M	395.930000
515.1M	140.980000
515.2M	201.400000
515.3M	302.090000
515.4M	382.650000
515.5M	483.350000
515.6M	538.730000
515.7M	619.290000
515.8M	538.730000
517.1M	509.760000
517.2M	1,372.420000
517.3M	1,568.480000
517.4M	490.150000
517.5M	509.760000
517.6M	637.190000
518.1M	958.880000
518.2M	1,917.760000
518.3M	1,917.760000
518.4M	1,917.760000
519.1M	324.160000
519.2M	324.160000
519.3M	319.840000
519.4M	283.100000
519.5M	399.800000
519.6M	259.330000
521.1M	73.160000
521.2M	73.160000
521.3M	61.910000
521.4M	74.100000
521.5M	87.230000
521.6M	98.490000
521.7M	98.490000
523.1M	93.690000
525.1M	28.730000
526.1M	156.130000
527.1M	1,282.330000
527.2M	2,369.530000
528.1M	312.250000

528.2M	349.720000
528.3M	349.720000
528.4M	374.700000
529.1M	112.410000

501	501				
501.1		.100000 x	592.284235 =	59.228424	
501.3		.150000 x	587.588235 =	88.138235	
501.4		.150000 x	547.600262 =	82.140039	
501.2		.600000 x	718.908574 =	431.345144	
			H. . =	660.851842	
501.1	501.1				
211		146.190706 x	1.271500 =	185.881483	
114		6.670000 x	23.647167 =	157.726604	
211		14.619071 x	1.271500 =	18.588149	
501.1M		.800000 x	287.610000 =	230.088000	
			H. . =	592.284235	
501.2	501.2				
211		216.578823 x	1.271500 =	275.379973	
114		6.670000 x	23.647167 =	157.726604	
501.2M		.800000 x	322.830000 =	258.264000	
211		21.657882 x	1.271500 =	27.537997	
			H. . =	718.908574	
501.3	501.3				
211		14.619071 x	1.271500 =	18.588149	
114		6.670000 x	23.647167 =	157.726604	
501.3M		.800000 x	281.740000 =	225.392000	
211		146.190706 x	1.271500 =	185.881483	
			H. . =	587.588235	
501.4	501.4				
211		164.599905 x	1.271500 =	209.288779	
211		16.459991 x	1.271500 =	20.928879	
501.4M		.800000 x	199.570000 =	159.656000	
114		6.670000 x	23.647167 =	157.726604	
			H. . =	547.600262	
502	502				
502.1		.200000 x	779.519360 =	155.903872	
502.3		.400000 x	1,298.963264 =	519.585306	
502.2		.400000 x	967.590665 =	387.036266	
			H. . =	1,062.525444	

502.1	502.1			
211		24.365118 x	1.271500 =	30.980248
118		2.000000 x	10.001019 =	20.002038
211		243.651176 x	1.271500 =	309.802470
114		6.670000 x	23.647167 =	157.726604
502.1M		.800000 x	326.260000 =	261.008000

			H. . =	779.519360
502.2	502.2			
211		291.027794 x	1.271500 =	370.041840
211		29.102779 x	1.271500 =	37.004183
114		6.670000 x	23.647167 =	157.726604
118		2.000000 x	10.001019 =	20.002038
502.2M		.800000 x	478.520000 =	382.816000

			H. . =	967.590665
502.3	502.3			
211		414.207001 x	1.271500 =	526.664202
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.647167 =	157.726604
502.3M		.800000 x	677.380000 =	541.904000
211		41.420700 x	1.271500 =	52.666420

			H. . =	1,298.963264
503	503			
502.3		.150000 x	1,298.963264 =	194.844490
503.4		.400000 x	1,599.114449 =	639.645780
503.6		.100000 x	1,334.464961 =	133.446496
503.5		.350000 x	2,434.948054 =	852.231819

			H. . =	1,820.168584
503.4	503.4			
211		50.083853 x	1.271500 =	63.681619
211		500.838528 x	1.271500 =	636.816188
502.4M		.800000 x	901.110000 =	720.888000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.647167 =	157.726604

			H. . =	1,599.114449
503.5	503.5			
211		703.881180 x	1.271500 =	894.984920
118		2.000000 x	10.001019 =	20.002038
211		70.388118 x	1.271500 =	89.498492
114		6.670000 x	23.647167 =	157.726604
502.5M		.800000 x	1,590.920000 =	1,272.736000

			H. . =	2,434.948054

503.6 503.6

211	44.669383 x	1.271500 =	56.797120
211	446.693825 x	1.271500 =	567.971198
114	6.670000 x	23.647167 =	157.726604
118	2.000000 x	10.001019 =	20.002038
502.6M	.800000 x	664.960000 =	531.968000

H. . = 1,334.464961

504 504

504.1	.350000 x	751.271221 =	262.944927
504.4	.100000 x	704.669783 =	70.466978
504.2	.450000 x	953.962613 =	429.283176
504.3	.100000 x	689.767221 =	68.976722

H. . = 831.671804

504.1 504.1

211	254.480118 x	1.271500 =	323.571470
114	6.670000 x	23.647167 =	157.726604
504.1M	.800000 x	297.020000 =	237.616000
211	25.448012 x	1.271500 =	32.357147

H. . = 751.271221

504.2 504.2

211	319.453766 x	1.271500 =	406.185463
211	31.945376 x	1.271500 =	40.618546
504.2M	.800000 x	436.790000 =	349.432000
114	6.670000 x	23.647167 =	157.726604

H. . = 953.962613

504.3 504.3

211	25.448012 x	1.271500 =	32.357147
211	254.480118 x	1.271500 =	323.571470
114	6.670000 x	23.647167 =	157.726604
504.3M	.800000 x	220.140000 =	176.112000

H. . = 689.767221

504.4 504.4

211	237.153812 x	1.271500 =	301.541072
211	23.715381 x	1.271500 =	30.154107
114	6.670000 x	23.647167 =	157.726604
504.4M	.800000 x	269.060000 =	215.248000

H. . = 704.669783

505	505				
505.1		.500000 x	1,209.305336 =	604.652668	
505.2		.500000 x	1,307.297336 =	653.648668	
			H. . =	1,258.301336	
505.1	505.1				
211		35.735506 x	1.271500 =	45.437696	
118		4.000000 x	10.001019 =	40.004076	
114		6.670000 x	23.647167 =	157.726604	
505.1M		.800000 x	639.700000 =	511.760000	
211		357.355061 x	1.271500 =	454.376960	
			H. . =	1,209.305336	
505.2	505.2				
211		35.735506 x	1.271500 =	45.437696	
211		357.355061 x	1.271500 =	454.376960	
505.2M		.800000 x	762.190000 =	609.752000	
118		4.000000 x	10.001019 =	40.004076	
114		6.670000 x	23.647167 =	157.726604	
			H. . =	1,307.297336	
506	506				
506.1		.100000 x	425.753959 =	42.575396	
506.4		.350000 x	537.426934 =	188.099427	
506.2		.200000 x	472.068488 =	94.413698	
506.3		.350000 x	481.505209 =	168.526823	
			H. . =	493.615344	
506.1	506.1				
211		10.675531 x	1.271500 =	13.573938	
118		2.000000 x	10.001019 =	20.002038	
506.1M		.800000 x	123.390000 =	98.712000	
114		6.670000 x	23.647167 =	157.726604	
211		106.755312 x	1.271500 =	135.739379	
			H. . =	425.753959	
506.2	506.2				
211		13.373742 x	1.271500 =	17.004713	
506.2M		.800000 x	134.110000 =	107.288000	
114		6.670000 x	23.647167 =	157.726604	
118		2.000000 x	10.001019 =	20.002038	
211		133.737423 x	1.271500 =	170.047133	
			H. . =	472.068488	

506.3	506.3			
211		117.313529 x	1.271500 =	149.164152
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.647167 =	157.726604
506.3M		.800000 x	174.620000 =	139.696000
211		11.731353 x	1.271500 =	14.916415

			H. . =	481.505209
506.4	506.4			
211		14.312251 x	1.271500 =	18.198027
211		143.122505 x	1.271500 =	181.980265
506.4M		.800000 x	199.400000 =	159.520000
118		2.000000 x	10.001019 =	20.002038
114		6.670000 x	23.647167 =	157.726604

			H. . =	537.426934
507	507			
507.5		.100000 x	581.881551 =	58.188155
507.8		.100000 x	643.451966 =	64.345197
507.10		.250000 x	951.782261 =	237.945565
507.9		.350000 x	750.380999 =	262.633350
507.6		.100000 x	714.285919 =	71.428592
507.7		.100000 x	893.773976 =	89.377398

			H. . =	783.918256
507.10	507.10			
211		334.343559 x	1.271500 =	425.117835
118		2.000000 x	10.001019 =	20.002038
211		33.434356 x	1.271500 =	42.511784
114		6.670000 x	23.647167 =	157.726604
506.10M		.800000 x	383.030000 =	306.424000

			H. . =	951.782261
507.5	507.5			
211		187.701647 x	1.271500 =	238.662644
506.5M		.800000 x	177.030000 =	141.624000
114		6.670000 x	23.647167 =	157.726604
118		2.000000 x	10.001019 =	20.002038
211		18.770165 x	1.271500 =	23.866265

			H. . =	581.881551

507.6 507.6

211	263.955441 x	1.271500 =	335.619343
118	2.000000 x	10.001019 =	20.002038
114	6.670000 x	23.647167 =	157.726604
506.6M	.800000 x	209.220000 =	167.376000
211	26.395544 x	1.271500 =	33.561934

H. . = 714.285919

507.7 507.7

211	27.568679 x	1.271500 =	35.053575
211	275.686794 x	1.271500 =	350.535759
506.7M	.800000 x	413.070000 =	330.456000
118	2.000000 x	10.001019 =	20.002038
114	6.670000 x	23.647167 =	157.726604

H. . = 893.773976

507.8 507.8

211	191.221052 x	1.271500 =	243.137568
118	2.000000 x	10.001019 =	20.002038
211	19.122105 x	1.271500 =	24.313757
114	6.670000 x	23.647167 =	157.726604
506.8M	.800000 x	247.840000 =	198.272000

H. . = 643.451966

507.9 507.9

211	23.931960 x	1.271500 =	30.429487
211	239.319599 x	1.271500 =	304.294870
114	6.670000 x	23.647167 =	157.726604
118	2.000000 x	10.001019 =	20.002038
506.9M	.800000 x	297.410000 =	237.928000

H. . = 750.380999

508 508

508.1	.250000 x	367.824588 =	91.956147
508.4	.250000 x	471.041678 =	117.760420
508.2	.250000 x	419.976759 =	104.994190
508.3	.250000 x	427.792759 =	106.948190

H. . = 421.658946

508.1 508.1

211	28.155247 x	1.271500 =	35.799397
116	13.340000 x	20.290479 =	270.674990
115	2.000000 x	21.561131 =	43.122262
508.1M	.800000 x	18.310000 =	14.648000
211	2.815525 x	1.271500 =	3.579940

H. . = 367.824588

508.2 508.2

211	6.334931 x	1.271500 =	8.054865
211	63.349306 x	1.271500 =	80.548643
508.2M	.800000 x	21.970000 =	17.576000
116	13.340000 x	20.290479 =	270.674990
115	2.000000 x	21.561131 =	43.122262

H. . = 419.976759

508.3 508.3

211	63.349306 x	1.271500 =	80.548643
116	13.340000 x	20.290479 =	270.674990
211	6.334931 x	1.271500 =	8.054865
115	2.000000 x	21.561131 =	43.122262
508.3M	.800000 x	31.740000 =	25.392000

H. . = 427.792759

508.4 508.4

211	87.985147 x	1.271500 =	111.873114
211	8.798515 x	1.271500 =	11.187312
115	2.000000 x	21.561131 =	43.122262
116	13.340000 x	20.290479 =	270.674990
508.4M	.800000 x	42.730000 =	34.184000

H. . = 471.041678

509 509

509.1	.100000 x	582.029289 =	58.202929
509.4	.500000 x	622.371563 =	311.185782
509.2	.200000 x	525.232170 =	105.046434
509.3	.200000 x	647.826122 =	129.565224

H. . = 604.000369

509.1 509.1

211	284.259705 x	1.271500 =	361.436215
117	6.670000 x	16.609513 =	110.785452
509.1M	.800000 x	92.080000 =	73.664000
211	28.425971 x	1.271500 =	36.143622

H. . = 582.029289

509.2 509.2

211	243.651176 x	1.271500 =	309.802470
211	24.365118 x	1.271500 =	30.980248
509.2M	.800000 x	92.080000 =	73.664000
117	6.670000 x	16.609513 =	110.785452

H. . = 525.232170

509.3 509.3

211	32.892909 x	1.271500 =	41.823334
211	328.929089 x	1.271500 =	418.233337
117	6.670000 x	16.609513 =	110.785452
509.3M	.800000 x	96.230000 =	76.984000

H. . = 647.826122

509.4 509.4

211	308.624825 x	1.271500 =	392.416465
211	30.862482 x	1.271500 =	39.241646
117	6.670000 x	16.609513 =	110.785452
509.4M	.800000 x	99.910000 =	79.928000

H. . = 622.371563

511 511

511.1	.150000 x	389.220531 =	58.383080
511.4	.225000 x	392.613044 =	88.337935
511.5	.125000 x	394.205044 =	49.275631
511.6	.125000 x	392.796531 =	49.099566
511.3	.225000 x	392.196531 =	88.244219
511.2	.150000 x	387.554482 =	58.133172

H. . = 391.473603

511.1 511.1

211	.496326 x	1.271500 =	.631079
115	6.670000 x	21.561131 =	143.812744
112	13.340000 x	17.205541 =	229.521917
511.1M	.800000 x	11.180000 =	8.944000
211	4.963265 x	1.271500 =	6.310791

H. . = 389.220531

511.2 511.2

211	.377208 x	1.271500 =	.479620
115	6.670000 x	21.561131 =	143.812744
112	13.340000 x	17.205541 =	229.521917
511.2M	.800000 x	11.180000 =	8.944000
211	3.772081 x	1.271500 =	4.796201

H. . = 387.554482

511.3 511.3

211	4.963265 x	1.271500 =	6.310791
211	.496326 x	1.271500 =	.631079
511.3M	.800000 x	14.900000 =	11.920000
115	6.670000 x	21.561131 =	143.812744
112	13.340000 x	17.205541 =	229.521917

H. . = 392.196531

511.4 511.4

211	5.261061 x	1.271500 =	6.689439
115	6.670000 x	21.561131 =	143.812744
112	13.340000 x	17.205541 =	229.521917
511.4M	.800000 x	14.900000 =	11.920000
211	.526106 x	1.271500 =	.668944

H. . = 392.613044

511.5 511.5

211	5.261061 x	1.271500 =	6.689439
115	6.670000 x	21.561131 =	143.812744
112	13.340000 x	17.205541 =	229.521917
511.5M	.800000 x	16.890000 =	13.512000
211	.526106 x	1.271500 =	.668944

H. . = 394.205044

511.6 511.6

211	4.963265 x	1.271500 =	6.310791
112	13.340000 x	17.205541 =	229.521917
511.6M	.800000 x	15.650000 =	12.520000
115	6.670000 x	21.561131 =	143.812744
211	.496326 x	1.271500 =	.631079

H. . = 392.796531

512 512

512.1	.200000 x	105.193479 =	21.038696
512.4	.200000 x	156.264589 =	31.252918
512.5	.200000 x	158.788906 =	31.757781
512.2	.200000 x	109.339953 =	21.867991
512.3	.200000 x	113.126427 =	22.625285

H. . = 128.542671

512.1 512.1

211	1.804824 x	1.271500 =	2.294834
117	3.000000 x	16.609513 =	49.828539
112	3.000000 x	17.205541 =	51.616623
512.1M	.800000 x	1.530000 =	1.224000
211	.180482 x	1.271500 =	.229483

H. . = 105.193479

512.2 512.2

211	4.512059 x	1.271500 =	5.737083
211	.451206 x	1.271500 =	.573708
512.2M	.800000 x	1.980000 =	1.584000
117	3.000000 x	16.609513 =	49.828539
112	3.000000 x	17.205541 =	51.616623

H. . = 109.339953

512.3 512.3

211	.721929 x	1.271500 =	.917933
117	3.000000 x	16.609513 =	49.828539
211	7.219294 x	1.271500 =	9.179332
112	3.000000 x	17.205541 =	51.616623
512.3M	.800000 x	1.980000 =	1.584000

H. . = 113.126427

512.4 512.4

211	1.353618 x	1.271500 =	1.721125
211	13.536176 x	1.271500 =	17.211248
112	4.000000 x	17.205541 =	68.822164
117	4.000000 x	16.609513 =	66.438052
512.4M	.800000 x	2.590000 =	2.072000

H. . = 156.264589

512.5 512.5

211	15.341000 x	1.271500 =	19.506082
117	4.000000 x	16.609513 =	66.438052
112	4.000000 x	17.205541 =	68.822164
512.5M	.800000 x	2.590000 =	2.072000
211	1.534100 x	1.271500 =	1.950608

H. . = 158.788906

512A 512A

512.1	.333333 x	105.193479 =	35.064458
512.2	.333333 x	109.339953 =	36.446615
512.3	.333333 x	113.126427 =	37.708771

H. . = 109.219844

512B 512B

512.4	.500000 x	156.264589 =	78.132295
512.5	.500000 x	158.788906 =	79.394453

H. . = 157.526748

513	513			
513.6		.250000 x	210.476016 =	52.619004
513.9		.250000 x	275.450524 =	68.862631
513.8		.250000 x	261.735415 =	65.433854
513.7		.250000 x	223.097598 =	55.774400

H. . = 242.689888

513.6	513.6			
211		2.707235 x	1.271500 =	3.442249
117		5.000000 x	16.609513 =	83.047565
112		5.000000 x	17.205541 =	86.027705
211		27.072353 x	1.271500 =	34.422497
512.6M		.800000 x	4.420000 =	3.536000

H. . = 210.476016

513.7	513.7			
211		3.609647 x	1.271500 =	4.589666
512.7M		.800000 x	4.420000 =	3.536000
117		5.000000 x	16.609513 =	83.047565
112		5.000000 x	17.205541 =	86.027705
211		36.096470 x	1.271500 =	45.896662

H. . = 223.097598

513.8	513.8			
211		1.714582 x	1.271500 =	2.180091
211		17.145823 x	1.271500 =	21.800914
512.8M		.800000 x	15.260000 =	12.208000
117		6.670000 x	16.609513 =	110.785452
112		6.670000 x	17.205541 =	114.760958

H. . = 261.735415

513.9	513.9			
211		23.462706 x	1.271500 =	29.832831
211		2.346271 x	1.271500 =	2.983284
117		6.670000 x	16.609513 =	110.785452
112		6.670000 x	17.205541 =	114.760958
512.9M		.800000 x	21.360000 =	17.088000

H. . = 275.450524

513A	513A			
513.6		.500000 x	210.476016 =	105.238008
513.7		.500000 x	223.097598 =	111.548799

H. . = 216.786807

513B 513B

513.9 1.000000 x 275.450524 = 275.450524

H. . = 275.450524

514 514

514.1 .150000 x 592.341492 = 88.851224

514.3 .150000 x 672.225865 = 100.833880

514.4 .250000 x 743.006985 = 185.751746

514.5 .300000 x 884.628850 = 265.388655

514.2 .150000 x 608.692916 = 91.303937

H. . = 732.129442

514.1 514.1

211 5.865676 x 1.271500 = 7.458207

114 13.340000 x 23.647167 = 315.453208

514.1M .800000 x 243.560000 = 194.848000

211 58.656765 x 1.271500 = 74.582077

H. . = 592.341492

514.2 514.2

211 66.778471 x 1.271500 = 84.908826

211 6.677847 x 1.271500 = 8.490882

514.2M .800000 x 249.800000 = 199.840000

114 13.340000 x 23.647167 = 315.453208

H. . = 608.692916

514.3 514.3

211 7.219294 x 1.271500 = 9.179332

211 72.192941 x 1.271500 = 91.793324

114 13.340000 x 23.647167 = 315.453208

514.3M .800000 x 319.750000 = 255.800000

H. . = 672.225865

514.4 514.4

211 112.801471 x 1.271500 = 143.427070

211 11.280147 x 1.271500 = 14.342707

114 13.340000 x 23.647167 = 315.453208

514.4M .800000 x 337.230000 = 269.784000

H. . = 743.006985

514.5 514.5

211	18.048235 x	1.271500 =	22.948331
114	13.340000 x	23.647167 =	315.453208
514.5M	.800000 x	395.930000 =	316.744000
211	180.482353 x	1.271500 =	229.483312

H. . = 884.628850

515 515

515.1	.200000 x	383.599979 =	76.719996
515.2	.200000 x	470.305590 =	94.061118
515.4	.200000 x	691.035083 =	138.207017
515.5	.200000 x	817.032777 =	163.406555
515.3	.200000 x	625.577357 =	125.115471

H. . = 597.510157

515.1 515.1

211	8.085609 x	1.271500 =	10.280852
515.1M	.800000 x	140.980000 =	112.784000
211	80.856094 x	1.271500 =	102.808524
114	6.670000 x	23.647167 =	157.726604

H. . = 383.599979

515.2 515.2

211	10.828941 x	1.271500 =	13.768998
211	108.289412 x	1.271500 =	137.689987
114	6.670000 x	23.647167 =	157.726604
515.2M	.800000 x	201.400000 =	161.120000

H. . = 470.305590

515.3 515.3

211	16.171219 x	1.271500 =	20.561705
515.3M	.800000 x	302.090000 =	241.672000
114	6.670000 x	23.647167 =	157.726604
211	161.712189 x	1.271500 =	205.617048

H. . = 625.577357

515.4 515.4

211	16.243412 x	1.271500 =	20.653498
114	6.670000 x	23.647167 =	157.726604
515.4M	.800000 x	382.650000 =	306.120000
211	162.434118 x	1.271500 =	206.534981

H. . = 691.035083

515.5 515.5

211	194.920940 x	1.271500 =	247.841975
515.5M	.800000 x	483.350000 =	386.680000
114	6.670000 x	23.647167 =	157.726604
211	19.492094 x	1.271500 =	24.784198

H. . = 817.032777

516 516

515.5	.150000 x	817.032777 =	122.554917
516.6	.150000 x	881.531311 =	132.229697
516.8	.350000 x	960.289984 =	336.101494
516.7	.350000 x	1,031.806069 =	361.132124

H. . = 952.018232

516.6 516.6

211	209.359530 x	1.271500 =	266.200642
114	6.670000 x	23.647167 =	157.726604
515.6M	.800000 x	538.730000 =	430.984000
211	20.935953 x	1.271500 =	26.620064

H. . = 881.531311

516.7 516.7

211	27.072353 x	1.271500 =	34.422497
114	6.670000 x	23.647167 =	157.726604
515.7M	.800000 x	619.290000 =	495.432000
211	270.723530 x	1.271500 =	344.224968

H. . = 1,031.806069

516.8 516.8

211	265.670025 x	1.271500 =	337.799437
114	6.670000 x	23.647167 =	157.726604
211	26.567002 x	1.271500 =	33.779943
515.8M	.800000 x	538.730000 =	430.984000

H. . = 960.289984

517 517

517.1	.100000 x	1,257.164149 =	125.716415
517.2	.250000 x	2,237.588540 =	559.397135
517.3	.250000 x	2,571.138688 =	642.784672
517.4	.100000 x	1,146.814285 =	114.681429
517.6	.200000 x	1,422.216060 =	284.443212
517.5	.100000 x	1,225.610194 =	122.561019

H. . = 1,849.583882

517.1 517.1

211	15.792206 x	1.271500 =	20.079790
111	20.010000 x	15.643441 =	313.025254
114	13.340000 x	23.647167 =	315.453208
211	157.922058 x	1.271500 =	200.797897
517.1M	.800000 x	509.760000 =	407.808000

H. . = 1,257.164149

517.2 517.2

211	365.476765 x	1.271500 =	464.703707
114	13.340000 x	23.647167 =	315.453208
111	20.010000 x	15.643441 =	313.025254
211	36.547677 x	1.271500 =	46.470371
517.2M	.800000 x	1,372.420000 =	1,097.936000

H. . = 2,237.588540

517.3 517.3

211	49.181441 x	1.271500 =	62.534202
114	13.340000 x	23.647167 =	315.453208
111	20.010000 x	15.643441 =	313.025254
517.3M	.800000 x	1,568.480000 =	1,254.784000
211	491.814411 x	1.271500 =	625.342024

H. . = 2,571.138688

517.4 517.4

211	9.024118 x	1.271500 =	11.474166
211	90.241177 x	1.271500 =	114.741657
517.4M	.800000 x	490.150000 =	392.120000
114	13.340000 x	23.647167 =	315.453208
111	20.010000 x	15.643441 =	313.025254

H. . = 1,146.814285

517.5 517.5

211	135.361765 x	1.271500 =	172.112484
114	13.340000 x	23.647167 =	315.453208
211	13.536176 x	1.271500 =	17.211248
111	20.010000 x	15.643441 =	313.025254
517.5M	.800000 x	509.760000 =	407.808000

H. . = 1,225.610194

517.6 517.6

211	20.304265 x	1.271500 =	25.816873
211	203.042646 x	1.271500 =	258.168724
111	20.010000 x	15.643441 =	313.025254
114	13.340000 x	23.647167 =	315.453208
517.6M	.800000 x	637.190000 =	509.752000

H. . = 1,422.216060

518 518

518.1	.250000 x	1,948.740114 =	487.185029
518.4	.250000 x	2,786.524972 =	696.631243
518.2	.250000 x	2,715.844114 =	678.961029
518.3	.250000 x	2,751.184543 =	687.796136

H. . = 2,550.573436

518.1 518.1

211	265.309059 x	1.271500 =	337.340469
118	6.670000 x	10.001019 =	66.706797
116	13.340000 x	20.290479 =	270.674990
114	20.010000 x	23.647167 =	473.179812
518.1M	.800000 x	958.880000 =	767.104000
211	26.530906 x	1.271500 =	33.734047

H. . = 1,948.740114

518.2 518.2

211	26.530906 x	1.271500 =	33.734047
211	265.309059 x	1.271500 =	337.340469
518.2M	.800000 x	1,917.760000 =	1,534.208000
118	6.670000 x	10.001019 =	66.706797
116	13.340000 x	20.290479 =	270.674990
114	20.010000 x	23.647167 =	473.179812

H. . = 2,715.844114

518.3 518.3

211	290.576588 x	1.271500 =	369.468132
118	6.670000 x	10.001019 =	66.706797
116	13.340000 x	20.290479 =	270.674990
211	29.057659 x	1.271500 =	36.946813
114	20.010000 x	23.647167 =	473.179812
518.3M	.800000 x	1,917.760000 =	1,534.208000

H. . = 2,751.184543

518.4 518.4

211	31.584412 x	1.271500 =	40.159580
211	315.844116 x	1.271500 =	401.595793
114	20.010000 x	23.647167 =	473.179812
118	6.670000 x	10.001019 =	66.706797
116	13.340000 x	20.290479 =	270.674990
518.4M	.800000 x	1,917.760000 =	1,534.208000

H. . = 2,786.524972

519 519

519.1	.050000 x	812.682882 =	40.634144
519.6	.300000 x	719.608646 =	215.882594
519.5	.100000 x	1,050.211800 =	105.021180
519.2	.050000 x	866.639374 =	43.331969
519.4	.200000 x	784.567205 =	156.913441
519.3	.300000 x	822.163232 =	246.648970

H. . = 808.432297

519.1 519.1

211	171.277754 x	1.271500 =	217.779664
116	13.340000 x	20.290479 =	270.674990
115	2.000000 x	21.561131 =	43.122262
519.1M	.800000 x	324.160000 =	259.328000
211	17.127775 x	1.271500 =	21.777966

H. . = 812.682882

519.2 519.2

211	234.627058 x	1.271500 =	298.328304
211	23.462706 x	1.271500 =	29.832831
519.2M	.800000 x	324.160000 =	259.328000
116	6.670000 x	20.290479 =	135.337495
115	6.670000 x	21.561131 =	143.812744

H. . = 866.639374

519.3 519.3

211	20.529868 x	1.271500 =	26.103727
116	6.670000 x	20.290479 =	135.337495
211	205.298676 x	1.271500 =	261.037267
115	6.670000 x	21.561131 =	143.812744
519.3M	.800000 x	319.840000 =	255.872000

H. . = 822.163232

519.4 519.4

211	199.433001 x	1.271500 =	253.579061
211	19.943300 x	1.271500 =	25.357906
115	6.670000 x	21.561131 =	143.812744
116	6.670000 x	20.290479 =	135.337495
519.4M	.800000 x	283.100000 =	226.480000

H. . = 784.567205

519.5 519.5

211	32.261220 x	1.271500 =	41.020141
116	6.670000 x	20.290479 =	135.337495
115	6.670000 x	21.561131 =	143.812744
519.5M	.800000 x	399.800000 =	319.840000
211	322.612206 x	1.271500 =	410.201420

H. . = 1,050.211800

519.6 519.6

211	16.658521 x	1.271500 =	21.181309
211	166.585213 x	1.271500 =	211.813098
115	6.670000 x	21.561131 =	143.812744
116	6.670000 x	20.290479 =	135.337495
519.6M	.800000 x	259.330000 =	207.464000

H. . = 719.608646

521 521

521.1	.250000 x	330.762322 =	82.690581
521.4	.150000 x	389.068738 =	58.360311
521.5	.150000 x	399.572738 =	59.935911
521.2	.250000 x	338.335273 =	84.583818
521.3	.200000 x	324.791503 =	64.958301

H. . = 350.528921

521.1 521.1

211	7.471969 x	1.271500 =	9.500609
118	1.000000 x	10.001019 =	10.001019
114	6.670000 x	23.647167 =	157.726604
521.1M	.800000 x	73.160000 =	58.528000
211	74.719694 x	1.271500 =	95.006091

H. . = 330.762322

521.2 521.2

211	80.134165 x	1.271500 =	101.890591
114	6.670000 x	23.647167 =	157.726604
521.2M	.800000 x	73.160000 =	58.528000
118	1.000000 x	10.001019 =	10.001019
211	8.013417 x	1.271500 =	10.189060

H. . = 338.335273

521.3 521.3

211	76.885483 x	1.271500 =	97.759892
118	1.000000 x	10.001019 =	10.001019
114	6.670000 x	23.647167 =	157.726604
521.3M	.800000 x	61.910000 =	49.528000
211	7.688548 x	1.271500 =	9.775989

H. . = 324.791503

521.4 521.4

211	11.586967 x	1.271500 =	14.732829
118	1.000000 x	10.001019 =	10.001019
114	6.670000 x	23.647167 =	157.726604
521.4M	.800000 x	74.100000 =	59.280000
211	115.869671 x	1.271500 =	147.328287

H. . = 389.068738

521.5 521.5

211	115.869671 x	1.271500 =	147.328287
211	11.586967 x	1.271500 =	14.732829
521.5M	.800000 x	87.230000 =	69.784000
118	1.000000 x	10.001019 =	10.001019
114	6.670000 x	23.647167 =	157.726604

H. . = 399.572738

522 522

522.6	.500000 x	495.825840 =	247.912920
522.7	.500000 x	489.767479 =	244.883740

H. . = 492.796660

522.6 522.6

211	17.109727 x	1.271500 =	21.755018
521.6M	.800000 x	98.490000 =	78.792000
118	2.000000 x	10.001019 =	20.002038
114	6.670000 x	23.647167 =	157.726604
211	171.097271 x	1.271500 =	217.550180

H. . = 495.825840

522.7 522.7

211	16.676569 x	1.271500 =	21.204257
114	6.670000 x	23.647167 =	157.726604
118	2.000000 x	10.001019 =	20.002038
521.7M	.800000 x	98.490000 =	78.792000
211	166.765694 x	1.271500 =	212.042580

H. . = 489.767479

523 523

523.1	1.000000 x	365.808697 =	365.808697
-------	------------	--------------	------------

H. . = 365.808697

523.1 523.1

211	54.144706 x	1.271500 =	68.844994
523.1M	.800000 x	93.690000 =	74.952000
117	6.670000 x	16.609513 =	110.785452
111	6.670000 x	15.643441 =	104.341751
211	5.414471 x	1.271500 =	6.884500

H. . = 365.808697

525 525

525.1	1.000000 x	257.140459 =	257.140459
-------	------------	--------------	------------

H. . = 257.140459

525.1 525.1

211	4.512059 x	1.271500 =	5.737083
118	6.670000 x	10.001019 =	66.706797
111	6.670000 x	15.643441 =	104.341751
525.1M	.800000 x	28.730000 =	22.984000
211	45.120588 x	1.271500 =	57.370828

H. . = 257.140459

526 526

526.1	1.000000 x	606.475227 =	606.475227
-------	------------	--------------	------------

H. . = 606.475227

526.1 526.1

211	243.651176 x	1.271500 =	309.802470
118	3.000000 x	10.001019 =	30.003057
117	6.670000 x	16.609513 =	110.785452
526.1M	.800000 x	156.130000 =	124.904000
211	24.365118 x	1.271500 =	30.980248

H. . = 606.475227

527	527			
527.1		.400000 x	2,207.602443 =	883.040977
527.2		.600000 x	3,228.821431 =	1,937.292859

H. . = 2,820.333836

527.1	527.1			
211		433.157646 x	1.271500 =	550.759947
114		16.680000 x	23.647167 =	394.434746
118		6.670000 x	10.001019 =	66.706797
211		43.315765 x	1.271500 =	55.075995
112		6.670000 x	17.205541 =	114.760958
527.1M		.800000 x	1,282.330000 =	1,025.864000

H. . = 2,207.602443

527.2	527.2			
211		54.144706 x	1.271500 =	68.844994
118		6.670000 x	10.001019 =	66.706797
114		16.680000 x	23.647167 =	394.434746
112		6.670000 x	17.205541 =	114.760958
211		541.447060 x	1.271500 =	688.449937
527.2M		.800000 x	2,369.530000 =	1,895.624000

H. . = 3,228.821431

528	528			
528.1		.250000 x	814.825241 =	203.706310
528.4		.250000 x	943.039050 =	235.759763
528.2		.250000 x	880.141670 =	220.035418
528.3		.250000 x	867.520089 =	216.880022

H. . = 876.381513

528.1	528.1			
211		7.941224 x	1.271500 =	10.097266
118		6.670000 x	10.001019 =	66.706797
114		6.670000 x	23.647167 =	157.726604
112		13.340000 x	17.205541 =	229.521917
528.1M		.800000 x	312.250000 =	249.800000
211		79.412235 x	1.271500 =	100.972657

H. . = 814.825241

528.2 528.2

211	10.467976 x	1.271500 =	13.310031
211	104.679765 x	1.271500 =	133.100321
528.2M	.800000 x	349.720000 =	279.776000
118	6.670000 x	10.001019 =	66.706797
114	6.670000 x	23.647167 =	157.726604
112	13.340000 x	17.205541 =	229.521917

H. . = 880.141670

528.3 528.3

211	95.655647 x	1.271500 =	121.626155
118	6.670000 x	10.001019 =	66.706797
114	6.670000 x	23.647167 =	157.726604
211	9.565565 x	1.271500 =	12.162616
112	13.340000 x	17.205541 =	229.521917
528.3M	.800000 x	349.720000 =	279.776000

H. . = 867.520089

528.4 528.4

211	135.361765 x	1.271500 =	172.112484
211	13.536176 x	1.271500 =	17.211248
112	13.340000 x	17.205541 =	229.521917
118	6.670000 x	10.001019 =	66.706797
114	6.670000 x	23.647167 =	157.726604
528.4M	.800000 x	374.700000 =	299.760000

H. . = 943.039050

529 529

529.1	1.000000 x	771.018086 =	771.018086
-------	------------	--------------	------------

H. . = 771.018086

529.1 529.1

211	24.365118 x	1.271500 =	30.980248
117	6.670000 x	16.609513 =	110.785452
112	13.340000 x	17.205541 =	229.521917
529.1M	.800000 x	112.410000 =	89.928000
211	243.651176 x	1.271500 =	309.802470

H. . = 771.018086

2730A 2730A

234	48.000000 x	.857700 =	41.169600
513	.250000 x	242.689888 =	60.672472
511	.150000 x	391.473603 =	58.721040
517	1.000000 x	1,849.583882 =	1,849.583882
504	.400000 x	831.671804 =	332.668722
509	.400000 x	604.000369 =	241.600148
509	.200000 x	604.000369 =	120.800074
113	13.340000 x	20.290479 =	270.674990
112	6.670000 x	17.205541 =	114.760958
111	6.670000 x	15.643441 =	104.341751
251	.040000 x	290.000000 =	11.600000
235	24.000000 x	.622500 =	14.940000

B.T = 3,221.533637

2730B 2730B

234	1,000.000000 x	.857700 =	857.700000
113	140.000000 x	20.290479 =	2,840.667060
112	360.000000 x	17.205541 =	6,193.994760
506	2.500000 x	493.615344 =	1,234.038360
517	9.000000 x	1,849.583882 =	16,646.254938
515	7.000000 x	597.510157 =	4,182.571099
509	5.000000 x	604.000369 =	3,020.001845
509	2.209627 x	604.000369 =	1,334.615523
111	360.000000 x	15.643441 =	5,631.638760
252	2.000000 x	290.000000 =	580.000000
235	500.000000 x	.622500 =	311.250000
251	2.000000 x	290.000000 =	580.000000

B.T = 43,412.732345

2730 2730

222	350.000000 x	.116200 =	40.670000
625	.500000 x	16.649964 =	8.324982
630	.200000 x	.546949 =	.109390
623	.800000 x	15.121274 =	12.097019

B.T = 61.201391

611 611

111	1.400000 x	15.643441 =	21.900817
-----	------------	-------------	-----------

B.T = 21.900817

612 612

111	.250000 x	15.643441 =	3.910860
503	.000588 x	1,820.168584 =	1.070259
504	.000833 x	831.671804 =	.692783

B.T = 5.673902

613 613

111	.200000 x	15.643441 =	3.128688
518	.000500 x	2,550.573436 =	1.275287
504	.001000 x	831.671804 =	.831672
503	.000667 x	1,820.168584 =	1.214052

B.T = 6.449699

614 614

112	.080000 x	17.205541 =	1.376443
518	.002500 x	2,550.573436 =	6.376434
504	.001000 x	831.671804 =	.831672
509	.001950 x	604.000369 =	1.177801
503	.000909 x	1,820.168584 =	1.654533

B.T = 11.416883

615 615

112	.080000 x	17.205541 =	1.376443
518	.002500 x	2,550.573436 =	6.376434
504	.001000 x	831.671804 =	.831672
509	.001950 x	604.000369 =	1.177801
503	.000909 x	1,820.168584 =	1.654533

B.T = 11.416883

616 616

112	.080000 x	17.205541 =	1.376443
503	.000909 x	1,820.168584 =	1.654533
518	.002500 x	2,550.573436 =	6.376434
504	.001000 x	831.671804 =	.831672
509	.001950 x	604.000369 =	1.177801

B.T = 11.416883

617 617

111	.100000 x	15.643441 =	1.564344
503	.001000 x	1,820.168584 =	1.820169
518	.000625 x	2,550.573436 =	1.594108
504	.001000 x	831.671804 =	.831672

B.T = 5.810293

621 621

213	1.000000 x	1.949500 =	1.949500
519	.002500 x	808.432297 =	2.021081
111	.650000 x	15.643441 =	10.168237
116	.060000 x	20.290479 =	1.217429

B.T = 15.356246

622 622

213	1.000000 x	1.949500 =	1.949500
518	.001515 x	2,550.573436 =	3.864119
504	.001111 x	831.671804 =	.923987
519	.002500 x	808.432297 =	2.021081
509	.001950 x	604.000369 =	1.177801
503	.000909 x	1,820.168584 =	1.654533
116	.100000 x	20.290479 =	2.029048
112	.100000 x	17.205541 =	1.720554

B.T = 15.340623

623 623

213	1.000000 x	1.949500 =	1.949500
112	.100000 x	17.205541 =	1.720554
503	.000909 x	1,820.168584 =	1.654533
519	.002500 x	808.432297 =	2.021081
518	.001429 x	2,550.573436 =	3.644769
504	.001111 x	831.671804 =	.923987
509	.001950 x	604.000369 =	1.177801
116	.100000 x	20.290479 =	2.029048

B.T = 15.121274

624 624

213	1.000000 x	1.949500 =	1.949500
116	.100000 x	20.290479 =	2.029048
518	.001515 x	2,550.573436 =	3.864119
504	.001111 x	831.671804 =	.923987
519	.002500 x	808.432297 =	2.021081
509	.001950 x	604.000369 =	1.177801
503	.000909 x	1,820.168584 =	1.654533
112	.100000 x	17.205541 =	1.720554

B.T = 15.340623

625 625

213	1.000000 x	1.949500 =	1.949500
518	.002119 x	2,550.573436 =	5.404665
504	.000833 x	831.671804 =	.692783
519	.002500 x	808.432297 =	2.021081
509	.001950 x	604.000369 =	1.177801
503	.000909 x	1,820.168584 =	1.654533
116	.100000 x	20.290479 =	2.029048
112	.100000 x	17.205541 =	1.720554

B.T = 16.649964

626 626

509	.001786 x	604.000369 =	1.078745
504	.002000 x	831.671804 =	1.663344

B.T = 2.742088

630 630

512 .004255 x 128.542671 = .546949

B.T = .546949

641 641

231 .200000 x .927000 = .185400
111 .200000 x 15.643441 = 3.128688
113 .150000 x 20.290479 = 3.043572
252 .002500 x 290.000000 = .725000
251 .001500 x 290.000000 = .435000

B.T = 7.517660

642 642

231 .300000 x .927000 = .278100
113 .250000 x 20.290479 = 5.072620
111 .250000 x 15.643441 = 3.910860
252 .005000 x 290.000000 = 1.450000
251 .003000 x 290.000000 = .870000

B.T = 11.581580

651 651

221 150.000000 x .099900 = 14.985000
111 1.500000 x 15.643441 = 23.465162
112 .500000 x 17.205541 = 8.602771
625 1.000000 x 16.649964 = 16.649964
511 .040000 x 391.473603 = 15.658944
509 .002166 x 604.000369 = 1.308265
509 .007516 x 604.000369 = 4.539667
630 .600000 x .546949 = .328169
224 120.000000 x .070000 = 8.400000

B.T = 93.937941

652 652

221 650.000000 x .099900 = 64.935000
111 1.500000 x 15.643441 = 23.465162
511 .040000 x 391.473603 = 15.658944
509 .002166 x 604.000369 = 1.308265
509 .007516 x 604.000369 = 4.539667
630 .320000 x .546949 = .175024
625 1.000000 x 16.649964 = 16.649964
112 .500000 x 17.205541 = 8.602771

B.T = 135.334795

661	661			
353		.160000 x	3.630000 =	.580800
354		.220000 x	4.020000 =	.884400
113		1.100000 x	20.290479 =	22.319527
355		.250000 x	.121800 =	.030450

B.T = 23.815177

671	671			
215		.562500 x	1.118700 =	.629269
525		.000067 x	257.140459 =	.017228
111		.002000 x	15.643441 =	.031287
321		.550000 x	.594700 =	.327085

B.T = 1.004869

671.1	671.1			
215		.562500 x	1.118700 =	.629269
525		.000067 x	257.140459 =	.017228
111		.002000 x	15.643441 =	.031287

B.T = .677784

672	672			
215		.075000 x	1.118700 =	.083903
321		.940000 x	.594700 =	.559018
525		.000067 x	257.140459 =	.017228
111		.002000 x	15.643441 =	.031287

B.T = .691436

672.1	672.1			
215		.075000 x	1.118700 =	.083903
525		.000067 x	257.140459 =	.017228
111		.002000 x	15.643441 =	.031287

B.T = .132418

4311A	4311A			
321		80.000000 x	.594700 =	47.576000
616		.200000 x	11.416883 =	2.283377
615		.370000 x	11.416883 =	4.224247
527		.001786 x	2,820.333836 =	5.037116
504		.001786 x	831.671804 =	1.485366
626		.030000 x	2.742088 =	.082263
625		.500000 x	16.649964 =	8.324982

. = 69.013350

4311A.1 4311A.1

625	.500000 x	16.649964 =	8.324982
626	.030000 x	2.742088 =	.082263
504	.001786 x	831.671804 =	1.485366
527	.001786 x	2,820.333836 =	5.037116
616	.200000 x	11.416883 =	2.283377
615	.370000 x	11.416883 =	4.224247

. = 21.437350

4311B 4311B

321	80.000000 x	.594700 =	47.576000
626	.030000 x	2.742088 =	.082263
625	.500000 x	16.649964 =	8.324982
623	.370000 x	15.121274 =	5.594871
527	.001786 x	2,820.333836 =	5.037116
504	.001786 x	831.671804 =	1.485366
624	.200000 x	15.340623 =	3.068125

. = 71.168723

4311B.1 4311B.1

623	.370000 x	15.121274 =	5.594871
625	.500000 x	16.649964 =	8.324982
527	.001786 x	2,820.333836 =	5.037116
504	.001786 x	831.671804 =	1.485366
626	.030000 x	2.742088 =	.082263
624	.200000 x	15.340623 =	3.068125

. = 23.592723

4312 4312

509	.001622 x	604.000369 =	.979689
504	.001000 x	831.671804 =	.831672

. = 1.811360

4411A 4411A

321	80.000000 x	.594700 =	47.576000
616	.200000 x	11.416883 =	2.283377
615	.370000 x	11.416883 =	4.224247
626	.030000 x	2.742088 =	.082263
625	.500000 x	16.649964 =	8.324982
504	.001786 x	831.671804 =	1.485366
527	.001786 x	2,820.333836 =	5.037116

. = 69.013350

4411A.1 4411A.1

625	.500000 x	16.649964 =	8.324982
626	.030000 x	2.742088 =	.082263
527	.001786 x	2,820.333836 =	5.037116
616	.200000 x	11.416883 =	2.283377
615	.370000 x	11.416883 =	4.224247
504	.001786 x	831.671804 =	1.485366

. = 21.437350

4411B 4411B

321	80.000000 x	.594700 =	47.576000
527	.001786 x	2,820.333836 =	5.037116
504	.001786 x	831.671804 =	1.485366
625	.500000 x	16.649964 =	8.324982
623	.370000 x	15.121274 =	5.594871
624	.200000 x	15.340623 =	3.068125
626	.030000 x	2.742088 =	.082263

. = 71.168723

4411B.1 4411B.1

623	.370000 x	15.121274 =	5.594871
624	.200000 x	15.340623 =	3.068125
626	.030000 x	2.742088 =	.082263
625	.500000 x	16.649964 =	8.324982
527	.001786 x	2,820.333836 =	5.037116
504	.001786 x	831.671804 =	1.485366

. = 23.592723

4412 4412

509	.001622 x	604.000369 =	.979689
504	.001000 x	831.671804 =	.831672

. = 1.811360

4511A 4511A

321	90.000000 x	.594700 =	53.523000
616	.300000 x	11.416883 =	3.425065
615	.370000 x	11.416883 =	4.224247
527	.001786 x	2,820.333836 =	5.037116
504	.001786 x	831.671804 =	1.485366
626	.050000 x	2.742088 =	.137104
625	.450000 x	16.649964 =	7.492484

. = 75.324382

4511A.1	4511A.1			
625		.450000 x	16.649964 =	7.492484
626		.050000 x	2.742088 =	.137104
504		.001786 x	831.671804 =	1.485366
527		.001786 x	2,820.333836 =	5.037116
616		.300000 x	11.416883 =	3.425065
615		.370000 x	11.416883 =	4.224247

			. =	21.801382
4511B	4511B			
321		90.000000 x	.594700 =	53.523000
625		.450000 x	16.649964 =	7.492484
623		.370000 x	15.121274 =	5.594871
527		.001786 x	2,820.333836 =	5.037116
504		.001786 x	831.671804 =	1.485366
626		.050000 x	2.742088 =	.137104
624		.300000 x	15.340623 =	4.602187

			. =	77.872129
4511B.1	4511B.1			
623		.370000 x	15.121274 =	5.594871
527		.001786 x	2,820.333836 =	5.037116
504		.001786 x	831.671804 =	1.485366
626		.050000 x	2.742088 =	.137104
625		.450000 x	16.649964 =	7.492484
624		.300000 x	15.340623 =	4.602187

			. =	24.349129
4512	4512			
509		.001622 x	604.000369 =	.979689
504		.001000 x	831.671804 =	.831672

			. =	1.811360
1110	1110			
503		.000455 x	1,820.168584 =	.828177
501		.000250 x	660.851842 =	.165213

			T.E =	.993390
1121	1121			
112		.005000 x	17.205541 =	.086028
501		.000083 x	660.851842 =	.054851
503		.000714 x	1,820.168584 =	1.299600

			T.E =	1.440479

1122 1122

112	.005000 x	17.205541 =	.086028
509	.002000 x	604.000369 =	1.208001
507	.000385 x	783.918256 =	.301809
501	.000080 x	660.851842 =	.052868
505	.000316 x	1,258.301336 =	.397623
503	.000100 x	1,820.168584 =	.182017

T.E = 2.228345

1123.A 1123.A

112	.005000 x	17.205541 =	.086028
503	.000500 x	1,820.168584 =	.910084
509	.001429 x	604.000369 =	.863117
507	.000769 x	783.918256 =	.602833
501	.000080 x	660.851842 =	.052868

T.E = 2.514930

1123.B 1123.B

509	.000870 x	604.000369 =	.525480
-----	-----------	--------------	---------

T.E = .525480

1131 1131

213	1.000000 x	1.949500 =	1.949500
519	.000952 x	808.432297 =	.769628
112	.030000 x	17.205541 =	.516166
503	.000909 x	1,820.168584 =	1.654533

T.E = 4.889827

1132 1132

213	1.000000 x	1.949500 =	1.949500
504	.001000 x	831.671804 =	.831672
503	.000909 x	1,820.168584 =	1.654533
112	.120000 x	17.205541 =	2.064665
519	.000952 x	808.432297 =	.769628
509	.002000 x	604.000369 =	1.208001

T.E = 8.477998

1133.A 1133.A

213	1.000000 x	1.949500 =	1.949500
112	.120000 x	17.205541 =	2.064665
504	.001000 x	831.671804 =	.831672
519	.000952 x	808.432297 =	.769628
509	.001176 x	604.000369 =	.710304
503	.000909 x	1,820.168584 =	1.654533

T.E = 7.980302

1133.B 1133.B

509 .000870 x 604.000369 = .525480

T.E = .525480

1140 1140

112 .006000 x 17.205541 = .103233
522 .000133 x 492.796660 = .065542
501 .000050 x 660.851842 = .033043

T.E = .201818

1211 1211

112 .200000 x 17.205541 = 3.441108
501 .001538 x 660.851842 = 1.016390
507 .001538 x 783.918256 = 1.205666

T.E = 5.663165

1212 1212

112 .200000 x 17.205541 = 3.441108
507 .001538 x 783.918256 = 1.205666
501 .001538 x 660.851842 = 1.016390
509 .002298 x 604.000369 = 1.387993

T.E = 7.051157

1220 1220

213 1.000000 x 1.949500 = 1.949500
116 .060000 x 20.290479 = 1.217429
519 .002222 x 808.432297 = 1.796337
111 .500000 x 15.643441 = 7.821721
112 .060000 x 17.205541 = 1.032332

T.E = 13.817318

1310 1310

112 .070000 x 17.205541 = 1.204388
501 .000385 x 660.851842 = .254428

T.E = 1.458816

1320 1320

112 1.500000 x 17.205541 = 25.808312

T.E = 25.808312

1410 1410

112	.005000 x	17.205541 =	.086028
501	.000083 x	660.851842 =	.054851
503	.000833 x	1,820.168584 =	1.516200

T.E = 1.657079

1420 1420

112	.006000 x	17.205541 =	.103233
509	.001826 x	604.000369 =	1.102905
503	.000208 x	1,820.168584 =	.378595
501	.000050 x	660.851842 =	.033043
507	.000385 x	783.918256 =	.301809
505	.000316 x	1,258.301336 =	.397623

T.E = 2.317207

1510 1510

112	.007000 x	17.205541 =	.120439
509	.001429 x	604.000369 =	.863117
504	.000714 x	831.671804 =	.593814
503	.000385 x	1,820.168584 =	.700765

T.E = 2.278134

1520 1520

509	.000833 x	604.000369 =	.503132
-----	-----------	--------------	---------

T.E = .503132

1530 1530

630	.150000 x	.546949 =	.082042
502	.000208 x	1,062.525444 =	.221005
501	.000250 x	660.851842 =	.165213
509	.000413 x	604.000369 =	.249452
522	.000556 x	492.796660 =	.273995

T.E = .991708

1610 1610

111	.040000 x	15.643441 =	.625738
503	.000111 x	1,820.168584 =	.202039
507	.000118 x	783.918256 =	.092502
1122	.200000 x	2.228345 =	.445669
501	.000050 x	660.851842 =	.033043

T.E = 1.398990

1620 1620

112	.200000 x	17.205541 =	3.441108
1122	1.000000 x	2.228345 =	2.228345
501	.000714 x	660.851842 =	.471848

T.E = 6.141301

2111 2111

112	.010000 x	17.205541 =	.172055
503	.001053 x	1,820.168584 =	1.916638
507	.000667 x	783.918256 =	.522873
501	.000500 x	660.851842 =	.330426
509	.002124 x	604.000369 =	1.282897

T.E = 4.224889

2112 2112

213	1.000000 x	1.949500 =	1.949500
112	.250000 x	17.205541 =	4.301385
507	.000667 x	783.918256 =	.522873
519	.002041 x	808.432297 =	1.650010
509	.002124 x	604.000369 =	1.282897
503	.001613 x	1,820.168584 =	2.935932
116	.060000 x	20.290479 =	1.217429

T.E = 13.860026

2151 2151

213	.300000 x	1.949500 =	.584850
112	.100000 x	17.205541 =	1.720554
112	.200000 x	17.205541 =	3.441108
113	.030000 x	20.290479 =	.608714
112	.100000 x	17.205541 =	1.720554
507	.003333 x	783.918256 =	2.612800
519	.001200 x	808.432297 =	.970119
509	.002124 x	604.000369 =	1.282897

T.E = 12.941596

2152 2152

112	.200000 x	17.205541 =	3.441108
507	.006667 x	783.918256 =	5.226383
509	.003196 x	604.000369 =	1.930385
112	.100000 x	17.205541 =	1.720554

T.E = 12.318430

2211 2211

244	1.000000 x	2.700000 =	2.700000
515	.000004 x	597.510157 =	.002390
515	.000004 x	597.510157 =	.002390
509	.000051 x	604.000369 =	.030804
112	.003000 x	17.205541 =	.051617
112	.002000 x	17.205541 =	.034411

T.E = 2.821612

2212 2212

244	.125000 x	2.700000 =	.337500
112	.007000 x	17.205541 =	.120439
515	.000008 x	597.510157 =	.004780
509	.000051 x	604.000369 =	.030804

T.E = .493523

2213 2213

236	3.000000 x	.622500 =	1.867500
517	.016667 x	1,849.583882 =	30.827015
515	.016667 x	597.510157 =	9.958702
113	.300000 x	20.290479 =	6.087144
111	.300000 x	15.643441 =	4.693032

T.E = 53.433392

2214 2214

111	.170000 x	15.643441 =	2.659385
515	.016667 x	597.510157 =	9.958702
113	.110000 x	20.290479 =	2.231953
111	.200000 x	15.643441 =	3.128688
113	.200000 x	20.290479 =	4.058096

T.E = 22.036823

2251 2251

111	.450000 x	15.643441 =	7.039548
112	.450000 x	17.205541 =	7.742493
509	.007516 x	604.000369 =	4.539667
621	1.050000 x	15.356246 =	16.124058

T.E = 35.445767

2252 2252

111	1.250000 x	15.643441 =	19.554301
621	1.050000 x	15.356246 =	16.124058
509	.007516 x	604.000369 =	4.539667
113	1.250000 x	20.290479 =	25.363099

T.E = 65.581125

2253 2253

111	1.500000 x	15.643441 =	23.465162
621	1.050000 x	15.356246 =	16.124058
652	.020000 x	135.334795 =	2.706696
509	.007891 x	604.000369 =	4.766167
651	.250000 x	93.937941 =	23.484485
113	2.500000 x	20.290479 =	50.726198
112	.200000 x	17.205541 =	3.441108

T.E = 124.713874

2254 2254

111	.750000 x	15.643441 =	11.732581
652	.100000 x	135.334795 =	13.533480
113	1.450000 x	20.290479 =	29.421195
509	.002630 x	604.000369 =	1.588521
621	.350000 x	15.356246 =	5.374686

T.E = 61.650462

2311 2311

243	1.020000 x	2.400000 =	2.448000
243	.080000 x	2.400000 =	.192000

T.E = 2.640000

2312 2312

112	.080000 x	17.205541 =	1.376443
113	.080000 x	20.290479 =	1.623238

T.E = 2.999682

2313 2313

111	.400000 x	15.643441 =	6.257376
509	.003326 x	604.000369 =	2.008905
611	1.050000 x	21.900817 =	22.995858
112	.400000 x	17.205541 =	6.882216

T.E = 38.144356

2350 2350

112	.100000 x	17.205541 =	1.720554
652	.022000 x	135.334795 =	2.977365
113	.250000 x	20.290479 =	5.072620

T.E = 9.770539

2411 2411

327	.500000 x	.540000 =	.270000
113	.180000 x	20.290479 =	3.652286

T.E = 3.922286

2412 2412

328	2.200000 x	1.840000 =	4.048000
111	.150000 x	15.643441 =	2.346516
329	2.000000 x	.730000 =	1.460000
2350	1.000000 x	9.770539 =	9.770539
113	.300000 x	20.290479 =	6.087144

T.E = 23.712199

2511 2511

221	200.000000 x	.099900 =	19.980000
623	.800000 x	15.121274 =	12.097019
625	.500000 x	16.649964 =	8.324982
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.016667 x	604.000369 =	10.066874
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
509	.006012 x	604.000369 =	3.631250
630	.250000 x	.546949 =	.136737
112	.400000 x	17.205541 =	6.882216
113	.250000 x	20.290479 =	5.072620

T.E = 72.376004

2512 2512

221	250.000000 x	.099900 =	24.975000
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
630	.250000 x	.546949 =	.136737
641	2.000000 x	7.517660 =	15.035320
625	.500000 x	16.649964 =	8.324982
509	.018182 x	604.000369 =	10.981935
623	.800000 x	15.121274 =	12.097019
112	.500000 x	17.205541 =	8.602771
113	.500000 x	20.290479 =	10.145240

T.E = 100.114558

2521 2521

221	50.000000 x	.099900 =	4.995000
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
509	.006012 x	604.000369 =	3.631250
641	2.000000 x	7.517660 =	15.035320
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019
113	.500000 x	20.290479 =	10.145240
112	.500000 x	17.205541 =	8.602771
221	250.000000 x	.099900 =	24.975000

T.E = 105.109558

2522 2522

221	300.000000 x	.099900 =	29.970000
113	.800000 x	20.290479 =	16.232383
625	.500000 x	16.649964 =	8.324982
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
641	3.000000 x	7.517660 =	22.552980
630	.250000 x	.546949 =	.136737
623	.800000 x	15.121274 =	12.097019
112	.600000 x	17.205541 =	10.323325

T.E = 120.434916

2523 2523

221	300.000000 x	.099900 =	29.970000
641	3.000000 x	7.517660 =	22.552980
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
509	.001444 x	604.000369 =	.872177
509	.003758 x	604.000369 =	2.269833
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.018182 x	604.000369 =	10.981935
509	.006012 x	604.000369 =	3.631250
623	.800000 x	15.121274 =	12.097019
113	1.050000 x	20.290479 =	21.305003
112	.750000 x	17.205541 =	12.904156

T.E = 128.088367

2524 2524

221	300.000000 x	.099900 =	29.970000
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
641	1.300000 x	7.517660 =	9.772958
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019
113	.800000 x	20.290479 =	16.232383
112	1.200000 x	17.205541 =	20.646649

T.E = 117.978218

2531 2531

222	300.000000 x	.116200 =	34.860000
112	1.300000 x	17.205541 =	22.367203
113	.900000 x	20.290479 =	18.261431
630	.250000 x	.546949 =	.136737
509	.018182 x	604.000369 =	10.981935
509	.003758 x	604.000369 =	2.269833
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.001444 x	604.000369 =	.872177
509	.006012 x	604.000369 =	3.631250
641	1.300000 x	7.517660 =	9.772958
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019

T.E = 126.617820

2532 2532

222	300.000000 x	.116200 =	34.860000
509	.006012 x	604.000369 =	3.631250
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
509	.003758 x	604.000369 =	2.269833
641	4.000000 x	7.517660 =	30.070640
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
112	1.600000 x	17.205541 =	27.528866
623	.800000 x	15.121274 =	12.097019
113	.900000 x	20.290479 =	18.261431
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601

T.E = 152.077165

2533 2533

222	300.000000 x	.116200 =	34.860000
112	1.800000 x	17.205541 =	30.969974
623	.800000 x	15.121274 =	12.097019
630	.250000 x	.546949 =	.136737
509	.001444 x	604.000369 =	.872177
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.003758 x	604.000369 =	2.269833
509	.018182 x	604.000369 =	10.981935
641	8.000000 x	7.517660 =	60.141280
625	.500000 x	16.649964 =	8.324982
113	1.200000 x	20.290479 =	24.348575

T.E = 191.676057

2541 2541

222	300.000000 x	.116200 =	34.860000
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
509	.003758 x	604.000369 =	2.269833
641	4.500000 x	7.517660 =	33.829470
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019
113	1.200000 x	20.290479 =	24.348575
112	1.600000 x	17.205541 =	27.528866
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250

T.E = 161.923138

2542 2542

222	300.000000 x	.116200 =	34.860000
112	1.650000 x	17.205541 =	28.389143
623	.800000 x	15.121274 =	12.097019
509	.018182 x	604.000369 =	10.981935
509	.003758 x	604.000369 =	2.269833
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.001444 x	604.000369 =	.872177
630	.250000 x	.546949 =	.136737
642	4.500000 x	11.581580 =	52.117110
625	.500000 x	16.649964 =	8.324982
113	1.250000 x	20.290479 =	25.363099

T.E = 182.085579

2543 2543

222	300.000000 x	.116200 =	34.860000
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
641	5.000000 x	7.517660 =	37.588300
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019
112	1.550000 x	17.205541 =	26.668589
113	.500000 x	20.290479 =	10.145240
113	1.250000 x	20.290479 =	25.363099

T.E = 175.981455

2544 2544

222	300.000000 x	.116200 =	34.860000
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
509	.003758 x	604.000369 =	2.269833
113	1.250000 x	20.290479 =	25.363099
112	1.650000 x	17.205541 =	28.389143
625	.500000 x	16.649964 =	8.324982
642	5.000000 x	11.581580 =	57.907900
630	.250000 x	.546949 =	.136737
623	.800000 x	15.121274 =	12.097019
113	.700000 x	20.290479 =	14.203335

T.E = 202.079705

2545 2545

222	300.000000 x	.116200 =	34.860000
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
509	.003758 x	604.000369 =	2.269833
641	6.000000 x	7.517660 =	45.105960
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019
113	1.900000 x	20.290479 =	38.551910
112	1.650000 x	17.205541 =	28.389143
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250

T.E = 188.263241

2546 2546

222	300.000000 x	.116200 =	34.860000
112	1.850000 x	17.205541 =	31.830251
113	1.900000 x	20.290479 =	38.551910
509	.018182 x	604.000369 =	10.981935
509	.003758 x	604.000369 =	2.269833
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.001444 x	604.000369 =	.872177
630	.250000 x	.546949 =	.136737
641	6.000000 x	7.517660 =	45.105960
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019

T.E = 191.704349

2547 2547

222	300.000000 x	.116200 =	34.860000
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
509	.003758 x	604.000369 =	2.269833
641	5.000000 x	7.517660 =	37.588300
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
112	1.550000 x	17.205541 =	26.668589
623	.800000 x	15.121274 =	12.097019
113	1.900000 x	20.290479 =	38.551910
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250

T.E = 179.025027

2548 2548

222	300.000000 x	.116200 =	34.860000
112	1.950000 x	17.205541 =	33.550805
623	.800000 x	15.121274 =	12.097019
509	.018182 x	604.000369 =	10.981935
509	.003758 x	604.000369 =	2.269833
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.001444 x	604.000369 =	.872177
630	.250000 x	.546949 =	.136737
641	5.000000 x	7.517660 =	37.588300
625	.500000 x	16.649964 =	8.324982
113	2.400000 x	20.290479 =	48.697150

T.E = 196.052483

2551 2551

222	360.000000 x	.116200 =	41.832000
514	.002857 x	732.129442 =	2.091694
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
641	4.500000 x	7.517660 =	33.829470
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019
113	1.050000 x	20.290479 =	21.305003
112	1.550000 x	17.205541 =	26.668589

T.E = 164.991289

2561 2561

222	450.000000 x	.116200 =	52.290000
111	1.250000 x	15.643441 =	19.554301
112	1.800000 x	17.205541 =	30.969974
623	.800000 x	15.121274 =	12.097019
514	.003704 x	732.129442 =	2.711807
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
641	4.500000 x	7.517660 =	33.829470
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
113	2.800000 x	20.290479 =	56.813341

T.E = 235.433428

2562 2562

222	450.000000 x	.116200 =	52.290000
111	1.950000 x	15.643441 =	30.504710
514	.003704 x	732.129442 =	2.711807
504	.001143 x	831.671804 =	.950601
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
509	.006012 x	604.000369 =	3.631250
642	4.500000 x	11.581580 =	52.117110
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
113	2.800000 x	20.290479 =	56.813341
623	.800000 x	15.121274 =	12.097019
112	1.800000 x	17.205541 =	30.969974

T.E = 264.671477

2563 2563

222	450.000000 x	.116200 =	52.290000
111	1.950000 x	15.643441 =	30.504710
514	.003704 x	732.129442 =	2.711807
504	.001143 x	831.671804 =	.950601
509	.003758 x	604.000369 =	2.269833
509	.018182 x	604.000369 =	10.981935
509	.001444 x	604.000369 =	.872177
509	.006012 x	604.000369 =	3.631250
641	5.000000 x	7.517660 =	37.588300
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019
113	3.900000 x	20.290479 =	79.132868
113	.900000 x	20.290479 =	18.261431
112	1.800000 x	17.205541 =	30.969974

T.E = 290.723625

2564 2564

222	450.000000 x	.116200 =	52.290000
514	.003704 x	732.129442 =	2.711807
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
642	5.000000 x	11.581580 =	57.907900
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019
113	.900000 x	20.290479 =	18.261431
112	1.800000 x	17.205541 =	30.969974
113	3.900000 x	20.290479 =	79.132868
111	1.950000 x	15.643441 =	30.504710

T.E = 311.043225

2565 2565

222	450.000000 x	.116200 =	52.290000
514	.003704 x	732.129442 =	2.711807
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
641	6.000000 x	7.517660 =	45.105960
630	.250000 x	.546949 =	.136737
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019
113	4.700000 x	20.290479 =	95.365251
112	2.350000 x	17.205541 =	40.433021
111	2.350000 x	15.643441 =	36.762086

T.E = 311.932661

2566 2566

222	450.000000 x	.116200 =	52.290000
630	.250000 x	.546949 =	.136737
514	.003704 x	732.129442 =	2.711807
504	.001143 x	831.671804 =	.950601
509	.006012 x	604.000369 =	3.631250
509	.003758 x	604.000369 =	2.269833
509	.001444 x	604.000369 =	.872177
509	.018182 x	604.000369 =	10.981935
642	6.000000 x	11.581580 =	69.489480
625	.500000 x	16.649964 =	8.324982
623	.800000 x	15.121274 =	12.097019
113	4.700000 x	20.290479 =	95.365251
112	2.350000 x	17.205541 =	40.433021
111	2.350000 x	15.643441 =	36.762086

T.E = 336.316181

2611 2611

233	1.050000 x	.559100 =	.587055
113	.035000 x	20.290479 =	.710167

T.E = 1.297222

2612 2612

238	1.050000 x	.559100 =	.587055
113	.035000 x	20.290479 =	.710167

T.E = 1.297222

2620 2620

239	1.010000 x	8.300000 =	8.383000
113	.080000 x	20.290479 =	1.623238
113	.080000 x	20.290479 =	1.623238
239	.303000 x	8.300000 =	2.514900

T.E = 14.144377

2651 2651

235	1.050000 x	.622500 =	.653625
113	.100000 x	20.290479 =	2.029048

T.E = 2.682673

2652 2652

235	1.050000 x	.622500 =	.653625
661	.050000 x	23.815177 =	1.190759
113	.120000 x	20.290479 =	2.434857

T.E = 4.279241

2653 2653

241	1.050000 x	7.750000 =	8.137500
661	.120000 x	23.815177 =	2.857821
113	.800000 x	20.290479 =	16.232383

T.E = 27.227704

2671 2671

237	1.000000 x	1.218000 =	1.218000
113	.015000 x	20.290479 =	.304357

T.E = 1.522357

2672 2672

235	1.050000 x	.622500 =	.653625
661	.050000 x	23.815177 =	1.190759
113	.120000 x	20.290479 =	2.434857

T.E = 4.279241

2711 2711

2551	1.000000 x	164.991289 =	164.991289
------	------------	--------------	------------

T.E = 164.991289

2712 2712

2611	1.000000 x	1.297222 =	1.297222
------	------------	------------	----------

T.E = 1.297222

2713 2713

237	1.000000 x	1.218000 =	1.218000
113	.070000 x	20.290479 =	1.420334

T.E = 2.638334

2714 2714

112	1.900000 x	17.205541 =	32.690528
517	.015385 x	1,849.583882 =	28.455848
516	.015385 x	952.018232 =	14.646800

T.E = 75.793176

2731 2731

2730A	.149925 x	3,221.533637 =	482.988431
2730B	.000667 x	43,412.732345 =	28.956292
2730	1.000000 x	61.201391 =	61.201391

T.E = 573.146114

2732 2732

2730A	.179910 x	3,221.533637 =	579.586117
2730B	.000667 x	43,412.732345 =	28.956292
2730	1.000000 x	61.201391 =	61.201391

T.E = 669.743800

2733 2733

233	1.050000 x	.559100 =	.587055
113	.035000 x	20.290479 =	.710167

T.E = 1.297222

2734 2734

238	1.050000 x	.559100 =	.587055
113	.035000 x	20.290479 =	.710167

T.E = 1.297222

2811 2811

112	.170000 x	17.205541 =	2.924942
509	.002217 x	604.000369 =	1.339069
507	.001538 x	783.918256 =	1.205666
501	.000500 x	660.851842 =	.330426

T.E = 5.800103

2815 2815

111	.250000 x	15.643441 =	3.910860
509	.005261 x	604.000369 =	3.177646
112	.350000 x	17.205541 =	6.021939
623	.400000 x	15.121274 =	6.048510
509	.003006 x	604.000369 =	1.815625
625	.700000 x	16.649964 =	11.654975

T.E = 32.629555

2861 2861

221	6.000000 x	.099900 =	.599400
281	1.000000 x	21.300000 =	21.300000
113	.200000 x	20.290479 =	4.058096
111	.250000 x	15.643441 =	3.910860

T.E = 29.868356

2862 2862

221	8.000000 x	.099900 =	.799200
282	1.000000 x	30.000000 =	30.000000
113	.200000 x	20.290479 =	4.058096
111	.250000 x	15.643441 =	3.910860

T.E = 38.768156

2863 2863

221	8.000000 x	.099900 =	.799200
283	1.000000 x	36.300000 =	36.300000
113	.550000 x	20.290479 =	11.159763
111	.650000 x	15.643441 =	10.168237

T.E = 58.427200

2864 2864

221	16.000000 x	.099900 =	1.598400
113	.550000 x	20.290479 =	11.159763
111	.700000 x	15.643441 =	10.950409
284	1.000000 x	75.400000 =	75.400000

T.E = 99.108572

2881 2881

221	6.000000 x	.099900 =	.599400
261	1.000000 x	15.100000 =	15.100000
113	.200000 x	20.290479 =	4.058096
111	.250000 x	15.643441 =	3.910860

T.E = 23.668356

2882 2882

221	8.000000 x	.099900 =	.799200
262	1.000000 x	26.300000 =	26.300000
113	.200000 x	20.290479 =	4.058096
111	.250000 x	15.643441 =	3.910860

T.E = 35.068156

2883 2883

221	10.000000 x	.099900 =	.999000
113	.550000 x	20.290479 =	11.159763
111	.650000 x	15.643441 =	10.168237
263	1.000000 x	32.400000 =	32.400000

T.E = 54.727000

2884 2884

221	16.000000 x	.099900 =	1.598400
264	1.000000 x	64.100000 =	64.100000
113	.550000 x	20.290479 =	11.159763
111	.700000 x	15.643441 =	10.950409

T.E = 87.808572

2885 2885

221	20.000000 x	.099900 =	1.998000
265	1.000000 x	115.100000 =	115.100000
113	.750000 x	20.290479 =	15.217859
111	1.000000 x	15.643441 =	15.643441

T.E = 147.959300

2888 2888

221	26.000000 x	.099900 =	2.597400
111	1.400000 x	15.643441 =	21.900817
113	1.100000 x	20.290479 =	22.319527
271	1.000000 x	206.300000 =	206.300000

T.E = 253.117744

2911 2911

351	1.050000 x	775.000000 =	813.750000
113	5.000000 x	20.290479 =	101.452395

T.E = 915.202395

2912 2912

352	1.050000 x	1,045.000000 =	1,097.250000
113	5.000000 x	20.290479 =	101.452395

T.E = 1,198.702395

2921 2921

301	1.000000 x	3.860000 =	3.860000
2522	.005000 x	120.434916 =	.602175
111	.250000 x	15.643441 =	3.910860
652	.002000 x	135.334795 =	.270670
113	.250000 x	20.290479 =	5.072620

T.E = 13.716324

2922 2922

302	1.020000 x	6.360000 =	6.487200
652	.015000 x	135.334795 =	2.030022
111	.350000 x	15.643441 =	5.475204
113	.600000 x	20.290479 =	12.174287

T.E = 26.166714

2951 2951

512A	.150000 x	109.219844 =	16.382977
------	-----------	--------------	-----------

T.E = 16.382977

2952	2952			
512B		.150000 x	157.526748 =	23.629012

			T.E =	23.629012
2953	2953			
513A		.150000 x	216.786807 =	32.518021

			T.E =	32.518021
2954	2954			
513B		.150000 x	275.450524 =	41.317579

			T.E =	41.317579
3111A	3111A			
112		.020000 x	17.205541 =	.344111
522		.000263 x	492.796660 =	.129606
509		.000072 x	604.000369 =	.043488
509		.000193 x	604.000369 =	.116572
630		.020000 x	.546949 =	.010939
501		.000182 x	660.851842 =	.120275
614		.135000 x	11.416883 =	1.541279

			T.E =	2.306270
3111B	3111B			
112		.020000 x	17.205541 =	.344111
622		.135000 x	15.340623 =	2.070984
509		.000193 x	604.000369 =	.116572
501		.000182 x	660.851842 =	.120275
509		.000072 x	604.000369 =	.043488
522		.000263 x	492.796660 =	.129606
630		.020000 x	.546949 =	.010939

			T.E =	2.835975
3112	3112			
509		.000094 x	604.000369 =	.056776

			T.E =	.056776
3121A	3121A			
112		.200000 x	17.205541 =	3.441108
501		.001818 x	660.851842 =	1.201429
614		1.350000 x	11.416883 =	15.412792
509		.000722 x	604.000369 =	.436088
509		.001929 x	604.000369 =	1.165117
522		.002632 x	492.796660 =	1.297041
630		.200000 x	.546949 =	.109390

			T.E =	23.062964

3121B 3121B

112	.200000 x	17.205541 =	3.441108
622	1.350000 x	15.340623 =	20.709841
509	.000722 x	604.000369 =	.436088
509	.001929 x	604.000369 =	1.165117
501	.001818 x	660.851842 =	1.201429
522	.002632 x	492.796660 =	1.297041
630	.200000 x	.546949 =	.109390

T.E = 28.360013

3122 3122

509	.000940 x	604.000369 =	.567760
-----	-----------	--------------	---------

T.E = .567760

3211A 3211A

112	.025000 x	17.205541 =	.430139
509	.000193 x	604.000369 =	.116572
501	.000182 x	660.851842 =	.120275
614	.135000 x	11.416883 =	1.541279
509	.000072 x	604.000369 =	.043488
630	.020000 x	.546949 =	.010939
522	.000263 x	492.796660 =	.129606

T.E = 2.392297

3211B 3211B

112	.025000 x	17.205541 =	.430139
622	.135000 x	15.340623 =	2.070984
501	.000182 x	660.851842 =	.120275
509	.000072 x	604.000369 =	.043488
509	.000193 x	604.000369 =	.116572
522	.000263 x	492.796660 =	.129606
630	.020000 x	.546949 =	.010939

T.E = 2.922002

3212 3212

509	.000141 x	604.000369 =	.085164
-----	-----------	--------------	---------

T.E = .085164

3221 3221

622	.202500 x	15.340623 =	3.106476
509	.000250 x	604.000369 =	.151000
509	.000286 x	604.000369 =	.172744
501	.000250 x	660.851842 =	.165213
509	.000250 x	604.000369 =	.151000
509	.000469 x	604.000369 =	.283276
630	.100000 x	.546949 =	.054695
522	.000500 x	492.796660 =	.246398

T.E = 4.330803

3222 3222

221	1.000000 x	.099900 =	.099900
-----	------------	-----------	---------

T.E = .099900

3223 3223

509	.000141 x	604.000369 =	.085164
-----	-----------	--------------	---------

T.E = .085164

3231 3231

112	.025000 x	17.205541 =	.430139
522	.000286 x	492.796660 =	.140940
501	.000213 x	660.851842 =	.140761
509	.000054 x	604.000369 =	.032616
630	.015000 x	.546949 =	.008204

T.E = .752660

3232A 3232A

630	.200000 x	.546949 =	.109390
614	1.350000 x	11.416883 =	15.412792
509	.001929 x	604.000369 =	1.165117

T.E = 16.687299

3232B 3232B

622	1.350000 x	15.340623 =	20.709841
509	.001929 x	604.000369 =	1.165117
630	.200000 x	.546949 =	.109390

T.E = 21.984348

3233 3233

509	.000940 x	604.000369 =	.567760
-----	-----------	--------------	---------

T.E = .567760

3241A 3241A

112	.025000 x	17.205541 =	.430139
509	.000193 x	604.000369 =	.116572
509	.000072 x	604.000369 =	.043488
501	.000213 x	660.851842 =	.140761
614	.135000 x	11.416883 =	1.541279
630	.020000 x	.546949 =	.010939
522	.000286 x	492.796660 =	.140940

T.E = 2.424118

3241B 3241B

112	.025000 x	17.205541 =	.430139
509	.000072 x	604.000369 =	.043488
501	.000213 x	660.851842 =	.140761
509	.000193 x	604.000369 =	.116572
622	.135000 x	15.340623 =	2.070984
522	.000286 x	492.796660 =	.140940
630	.020000 x	.546949 =	.010939

T.E = 2.953823

3242 3242

509	.000094 x	604.000369 =	.056776
-----	-----------	--------------	---------

T.E = .056776

3311A 3311A

112	.025000 x	17.205541 =	.430139
501	.000213 x	660.851842 =	.140761
614	.135000 x	11.416883 =	1.541279
509	.000193 x	604.000369 =	.116572
509	.000072 x	604.000369 =	.043488
522	.000286 x	492.796660 =	.140940
630	.020000 x	.546949 =	.010939

T.E = 2.424118

3311B 3311B

112	.025000 x	17.205541 =	.430139
622	.135000 x	15.340623 =	2.070984
509	.000193 x	604.000369 =	.116572
509	.000072 x	604.000369 =	.043488
501	.000213 x	660.851842 =	.140761
522	.000286 x	492.796660 =	.140940
630	.020000 x	.546949 =	.010939

T.E = 2.953823

3312	3312			
509		.000094 x	604.000369 =	.056776

			T.E =	.056776
3321A	3321A			
112		.030000 x	17.205541 =	.516166
509		.000072 x	604.000369 =	.043488
501		.000213 x	660.851842 =	.140761
614		.135000 x	11.416883 =	1.541279
509		.000193 x	604.000369 =	.116572
630		.020000 x	.546949 =	.010939
522		.000286 x	492.796660 =	.140940

			T.E =	2.510146
3321B	3321B			
112		.030000 x	17.205541 =	.516166
630		.020000 x	.546949 =	.010939
501		.000213 x	660.851842 =	.140761
509		.000193 x	604.000369 =	.116572
509		.000072 x	604.000369 =	.043488
522		.000286 x	492.796660 =	.140940
622		.135000 x	15.340623 =	2.070984

			T.E =	3.039851
3322	3322			
509		.000094 x	604.000369 =	.056776

			T.E =	.056776
3401	3401			
111		1.300000 x	15.643441 =	20.336473
521		.014286 x	350.528921 =	5.007656
509		.000361 x	604.000369 =	.218044
112		.900000 x	17.205541 =	15.484987
630		.100000 x	.546949 =	.054695

			T.E =	41.101855
3402A	3402A			
509		.001929 x	604.000369 =	1.165117
614		1.350000 x	11.416883 =	15.412792

			T.E =	16.577909
3402B	3402B			
622		1.350000 x	15.340623 =	20.709841
509		.001929 x	604.000369 =	1.165117

			T.E =	21.874958

3403 3403

509 .000940 x 604.000369 = .567760

T.E = .567760

4110 4110

112 .008000 x 17.205541 = .137644

671 1.200000 x 1.004869 = 1.205843

526 .000100 x 606.475227 = .060648

523 .000143 x 365.808697 = .052311

T.E = 1.456445

4110.1 4110.1

112 .008000 x 17.205541 = .137644

526 .000100 x 606.475227 = .060648

671.1 1.200000 x .677784 = .813341

523 .000143 x 365.808697 = .052311

T.E = 1.063943

4120 4120

321 .500000 x .594700 = .297350

525 .000067 x 257.140459 = .017228

526 .000100 x 606.475227 = .060648

523 .000143 x 365.808697 = .052311

112 .006000 x 17.205541 = .103233

T.E = .530770

4120.1 4120.1

112 .006000 x 17.205541 = .103233

523 .000143 x 365.808697 = .052311

525 .000067 x 257.140459 = .017228

526 .000100 x 606.475227 = .060648

T.E = .233420

4131A 4131A

321 1.000000 x .594700 = .594700

509 .000014 x 604.000369 = .008456

112 .008000 x 17.205541 = .137644

522 .000143 x 492.796660 = .070470

509 .000028 x 604.000369 = .016912

509 .000143 x 604.000369 = .086372

616 .015000 x 11.416883 = .171253

525 .000067 x 257.140459 = .017228

526 .000143 x 606.475227 = .086726

523 .000143 x 365.808697 = .052311

504 .000143 x 831.671804 = .118929

T.E = 1.361002

4131A.1 4131A.1

112	.008000 x	17.205541 =	.137644
509	.000014 x	604.000369 =	.008456
616	.015000 x	11.416883 =	.171253
525	.000067 x	257.140459 =	.017228
526	.000143 x	606.475227 =	.086726
523	.000143 x	365.808697 =	.052311
504	.000143 x	831.671804 =	.118929
509	.000028 x	604.000369 =	.016912
522	.000143 x	492.796660 =	.070470
509	.000143 x	604.000369 =	.086372

T.E = .766302

4131B 4131B

321	1.000000 x	.594700 =	.594700
525	.000067 x	257.140459 =	.017228
526	.000143 x	606.475227 =	.086726
523	.000143 x	365.808697 =	.052311
509	.000143 x	604.000369 =	.086372
522	.000143 x	492.796660 =	.070470
624	.015000 x	15.340623 =	.230109
504	.000143 x	831.671804 =	.118929
509	.000014 x	604.000369 =	.008456
509	.000028 x	604.000369 =	.016912
112	.008000 x	17.205541 =	.137644

T.E = 1.419858

4131B.1 4131B.1

112	.008000 x	17.205541 =	.137644
525	.000067 x	257.140459 =	.017228
526	.000143 x	606.475227 =	.086726
523	.000143 x	365.808697 =	.052311
504	.000143 x	831.671804 =	.118929
509	.000014 x	604.000369 =	.008456
509	.000028 x	604.000369 =	.016912
509	.000143 x	604.000369 =	.086372
522	.000143 x	492.796660 =	.070470
624	.015000 x	15.340623 =	.230109

T.E = .825158

4132 4132

509	.000009 x	604.000369 =	.005436
-----	-----------	--------------	---------

T.E = .005436

4141A 4141A

112	.013000 x	17.205541 =	.223672
616	.012000 x	11.416883 =	.137003
615	.015000 x	11.416883 =	.171253
526	.000244 x	606.475227 =	.147980
523	.000143 x	365.808697 =	.052311
504	.000244 x	831.671804 =	.202928
509	.000244 x	604.000369 =	.147376
522	.000244 x	492.796660 =	.120242
672	1.500000 x	.691436 =	1.037154
509	.000038 x	604.000369 =	.022952
509	.000024 x	604.000369 =	.014496
671	1.200000 x	1.004869 =	1.205843

T.E = 3.483210

4141A.1 4141A.1

112	.013000 x	17.205541 =	.223672
671.1	1.200000 x	.677784 =	.813341
616	.012000 x	11.416883 =	.137003
615	.015000 x	11.416883 =	.171253
526	.000244 x	606.475227 =	.147980
523	.000143 x	365.808697 =	.052311
504	.000244 x	831.671804 =	.202928
509	.000024 x	604.000369 =	.014496
509	.000038 x	604.000369 =	.022952
509	.000244 x	604.000369 =	.147376
522	.000244 x	492.796660 =	.120242
672.1	1.500000 x	.132418 =	.198627

T.E = 2.252181

4141B 4141B

112	.013000 x	17.205541 =	.223672
509	.000038 x	604.000369 =	.022952
509	.000244 x	604.000369 =	.147376
526	.000244 x	606.475227 =	.147980
523	.000143 x	365.808697 =	.052311
504	.000244 x	831.671804 =	.202928
509	.000024 x	604.000369 =	.014496
623	.015000 x	15.121274 =	.226819
522	.000244 x	492.796660 =	.120242
624	.012000 x	15.340623 =	.184087
672	1.500000 x	.691436 =	1.037154
671	1.200000 x	1.004869 =	1.205843

T.E = 3.585860

4141B.1 4141B.1

112	.013000 x	17.205541 =	.223672
623	.015000 x	15.121274 =	.226819
526	.000244 x	606.475227 =	.147980
523	.000143 x	365.808697 =	.052311
504	.000244 x	831.671804 =	.202928
509	.000024 x	604.000369 =	.014496
509	.000038 x	604.000369 =	.022952
509	.000244 x	604.000369 =	.147376
522	.000244 x	492.796660 =	.120242
672.1	1.500000 x	.132418 =	.198627
671.1	1.200000 x	.677784 =	.813341
624	.012000 x	15.340623 =	.184087

T.E = 2.354831

4142 4142

509	.000017 x	604.000369 =	.010268
-----	-----------	--------------	---------

T.E = .010268

4211A 4211A

672	25.000000 x	.691436 =	17.285900
501	.007024 x	660.851842 =	4.641823
616	.300000 x	11.416883 =	3.425065
615	.700000 x	11.416883 =	7.991818
526	.002857 x	606.475227 =	1.732700
509	.001429 x	604.000369 =	.863117
522	.003846 x	492.796660 =	1.895296

T.E = 37.835719

4211A.1 4211A.1

672.1	25.000000 x	.132418 =	3.310450
522	.003846 x	492.796660 =	1.895296
509	.001429 x	604.000369 =	.863117
615	.700000 x	11.416883 =	7.991818
501	.007024 x	660.851842 =	4.641823
616	.300000 x	11.416883 =	3.425065
526	.002857 x	606.475227 =	1.732700

T.E = 23.860269

4211B 4211B

623	.700000 x	15.121274 =	10.584892
522	.003846 x	492.796660 =	1.895296
501	.007024 x	660.851842 =	4.641823
624	.300000 x	15.340623 =	4.602187
526	.002857 x	606.475227 =	1.732700
509	.001429 x	604.000369 =	.863117
672	25.000000 x	.691436 =	17.285900

T.E = 41.605914

4211B.1 4211B.1

623	.700000 x	15.121274 =	10.584892
501	.007024 x	660.851842 =	4.641823
526	.002857 x	606.475227 =	1.732700
509	.001429 x	604.000369 =	.863117
522	.003846 x	492.796660 =	1.895296
672.1	25.000000 x	.132418 =	3.310450
624	.300000 x	15.340623 =	4.602187

T.E = 27.630464

4212 4212

509	.000614 x	604.000369 =	.370856
-----	-----------	--------------	---------

T.E = .370856

4221A 4221A

672	37.000000 x	.691436 =	25.583132
615	.600000 x	11.416883 =	6.850130
501	.008226 x	660.851842 =	5.436167
616	.400000 x	11.416883 =	4.566753
522	.004348 x	492.796660 =	2.142680
526	.004000 x	606.475227 =	2.425901
509	.001429 x	604.000369 =	.863117

T.E = 47.867880

4221A.1 4221A.1

672.1	37.000000 x	.132418 =	4.899466
501	.008226 x	660.851842 =	5.436167
616	.400000 x	11.416883 =	4.566753
615	.600000 x	11.416883 =	6.850130
526	.004000 x	606.475227 =	2.425901
522	.004348 x	492.796660 =	2.142680
509	.001429 x	604.000369 =	.863117

T.E = 27.184214

4221B 4221B

623	.600000 x	15.121274 =	9.072764
501	.008226 x	660.851842 =	5.436167
526	.004000 x	606.475227 =	2.425901
509	.001429 x	604.000369 =	.863117
624	.400000 x	15.340623 =	6.136249
522	.004348 x	492.796660 =	2.142680
672	37.000000 x	.691436 =	25.583132

T.E = 51.660010

4221B.1 4221B.1

623	.600000 x	15.121274 =	9.072764
501	.008226 x	660.851842 =	5.436167
526	.004000 x	606.475227 =	2.425901
672.1	37.000000 x	.132418 =	4.899466
522	.004348 x	492.796660 =	2.142680
509	.001429 x	604.000369 =	.863117
624	.400000 x	15.340623 =	6.136249

T.E = 30.976344

4222 4222

509	.000614 x	604.000369 =	.370856
-----	-----------	--------------	---------

T.E = .370856

4231A 4231A

112	.005000 x	17.205541 =	.086028
616	.006000 x	11.416883 =	.068501
615	.025000 x	11.416883 =	.285422
526	.000222 x	606.475227 =	.134638
523	.000143 x	365.808697 =	.052311
509	.000044 x	604.000369 =	.026576
509	.000036 x	604.000369 =	.021744
509	.000357 x	604.000369 =	.215628
522	.000357 x	492.796660 =	.175928
672	2.500000 x	.691436 =	1.728590
112	.030000 x	17.205541 =	.516166

T.E = 3.311532

4231A.1 4231A.1

112	.005000 x	17.205541 =	.086028
509	.000357 x	604.000369 =	.215628
616	.006000 x	11.416883 =	.068501
615	.025000 x	11.416883 =	.285422
526	.000222 x	606.475227 =	.134638
523	.000143 x	365.808697 =	.052311
509	.000036 x	604.000369 =	.021744
522	.000357 x	492.796660 =	.175928
672.1	2.500000 x	.132418 =	.331045
112	.030000 x	17.205541 =	.516166
509	.000044 x	604.000369 =	.026576

T.E = 1.913987

4231B 4231B

112	.005000 x	17.205541 =	.086028
623	.025000 x	15.121274 =	.378032
672	2.500000 x	.691436 =	1.728590
526	.000222 x	606.475227 =	.134638
523	.000143 x	365.808697 =	.052311
509	.000357 x	604.000369 =	.215628
509	.000036 x	604.000369 =	.021744
509	.000044 x	604.000369 =	.026576
522	.000357 x	492.796660 =	.175928
624	.006000 x	15.340623 =	.092044
112	.030000 x	17.205541 =	.516166

T.E = 3.427684

4231B.1 4231B.1

112	.005000 x	17.205541 =	.086028
509	.000044 x	604.000369 =	.026576
526	.000222 x	606.475227 =	.134638
523	.000143 x	365.808697 =	.052311
509	.000357 x	604.000369 =	.215628
522	.000357 x	492.796660 =	.175928
672.1	2.500000 x	.132418 =	.331045
624	.006000 x	15.340623 =	.092044
509	.000036 x	604.000369 =	.021744
623	.025000 x	15.121274 =	.378032
112	.030000 x	17.205541 =	.516166

T.E = 2.030139

4232 4232

509	.000024 x	604.000369 =	.014496
-----	-----------	--------------	---------

T.E = .014496

4321A 4321A

521	.000128 x	350.528921 =	.044868
523	.000143 x	365.808697 =	.052311
4312	.071000 x	1.811360 =	.128607
4311A	.071000 x	69.013350 =	4.899948
528	.000128 x	876.381513 =	.112177
509	.000101 x	604.000369 =	.061004
522	.000128 x	492.796660 =	.063078

T.E = 5.361992

4321A.1 4321A.1

521	.000128 x	350.528921 =	.044868
4312	.071000 x	1.811360 =	.128607
4311A.1	.071000 x	21.437350 =	1.522052
528	.000128 x	876.381513 =	.112177
522	.000128 x	492.796660 =	.063078
523	.000143 x	365.808697 =	.052311
509	.000101 x	604.000369 =	.061004

T.E = 1.984096

4321B 4321B

521	.000128 x	350.528921 =	.044868
522	.000128 x	492.796660 =	.063078
4312	.071000 x	1.811360 =	.128607
4311B	.071000 x	71.168723 =	5.052979
528	.000128 x	876.381513 =	.112177
523	.000143 x	365.808697 =	.052311
509	.000101 x	604.000369 =	.061004

T.E = 5.515023

4321B.1 4321B.1

521	.000128 x	350.528921 =	.044868
4312	.071000 x	1.811360 =	.128607
4311B.1	.071000 x	23.592723 =	1.675083
528	.000128 x	876.381513 =	.112177
523	.000143 x	365.808697 =	.052311
509	.000101 x	604.000369 =	.061004
522	.000128 x	492.796660 =	.063078

T.E = 2.137127

4322 4322

509	.000049 x	604.000369 =	.029596
-----	-----------	--------------	---------

T.E = .029596

4421A 4421A

521	.000128 x	350.528921 =	.044868
528	.000128 x	876.381513 =	.112177
4411A	.071000 x	69.013350 =	4.899948
4312	.071000 x	1.811360 =	.128607
523	.000143 x	365.808697 =	.052311
509	.000101 x	604.000369 =	.061004
522	.000128 x	492.796660 =	.063078

T.E = 5.361992

4421A.1 4421A.1

521	.000128 x	350.528921 =	.044868
509	.000101 x	604.000369 =	.061004
522	.000128 x	492.796660 =	.063078
4412	.071000 x	1.811360 =	.128607
4411A.1	.071000 x	21.437350 =	1.522052
528	.000128 x	876.381513 =	.112177
523	.000143 x	365.808697 =	.052311

T.E = 1.984096

4421B 4421B

521	.000128 x	350.528921 =	.044868
522	.000128 x	492.796660 =	.063078
509	.000101 x	604.000369 =	.061004
523	.000143 x	365.808697 =	.052311
4411B	.071000 x	71.168723 =	5.052979
4412	.071000 x	1.811360 =	.128607
528	.000128 x	876.381513 =	.112177

T.E = 5.515023

4421B.1 4421B.1

521	.000128 x	350.528921 =	.044868
522	.000128 x	492.796660 =	.063078
509	.000101 x	604.000369 =	.061004
4412	.071000 x	1.811360 =	.128607
4411B.1	.071000 x	23.592723 =	1.675083
528	.000128 x	876.381513 =	.112177
523	.000143 x	365.808697 =	.052311

T.E = 2.137127

4422 4422

509	.000049 x	604.000369 =	.029596
-----	-----------	--------------	---------

T.E = .029596

4521A 4521A

521	.000128 x	350.528921 =	.044868
4512	.071000 x	1.811360 =	.128607
4511A	.071000 x	75.324382 =	5.348031
528	.000128 x	876.381513 =	.112177
522	.000128 x	492.796660 =	.063078
523	.000143 x	365.808697 =	.052311
509	.000101 x	604.000369 =	.061004

T.E = 5.810075

4521A.1 4521A.1

521	.000128 x	350.528921 =	.044868
523	.000143 x	365.808697 =	.052311
509	.000101 x	604.000369 =	.061004
4511A.1	.071000 x	21.801382 =	1.547898
4512	.071000 x	1.811360 =	.128607
528	.000128 x	876.381513 =	.112177
522	.000128 x	492.796660 =	.063078

T.E = 2.009942

4521B 4521B

521	.000128 x	350.528921 =	.044868
4512	.071000 x	1.811360 =	.128607
4511B	.071000 x	77.872129 =	5.528921
528	.000128 x	876.381513 =	.112177
523	.000143 x	365.808697 =	.052311
509	.000101 x	604.000369 =	.061004
522	.000128 x	492.796660 =	.063078

T.E = 5.990965

4521B.1 4521B.1

521	.000128 x	350.528921 =	.044868
509	.000101 x	604.000369 =	.061004
523	.000143 x	365.808697 =	.052311
4511B.1	.071000 x	24.349129 =	1.728788
4512	.071000 x	1.811360 =	.128607
528	.000128 x	876.381513 =	.112177
522	.000128 x	492.796660 =	.063078

T.E = 2.190832

4522 4522

509	.000049 x	604.000369 =	.029596
-----	-----------	--------------	---------

T.E = .029596

4611.1 4611.1

326	45.000000 x	1.310000 =	58.950000
522	.000667 x	492.796660 =	.328695
623	.033000 x	15.121274 =	.499002
113	.100000 x	20.290479 =	2.029048
529	.002857 x	771.018086 =	2.202799
4120.1	1.000000 x	.233420 =	.233420
525	.000286 x	257.140459 =	.073542
509	.000046 x	604.000369 =	.027784
617	.013000 x	5.810293 =	.075534

T.E = 64.419824

4611A 4611A

321	3.000000 x	.594700 =	1.784100
326	45.000000 x	1.310000 =	58.950000
4120	1.000000 x	.530770 =	.530770
529	.002857 x	771.018086 =	2.202799
525	.000286 x	257.140459 =	.073542
509	.000046 x	604.000369 =	.027784
522	.000667 x	492.796660 =	.328695
623	.033000 x	15.121274 =	.499002
617	.013000 x	5.810293 =	.075534
113	.100000 x	20.290479 =	2.029048

T.E = 66.501274

4612 4612

509	.000040 x	604.000369 =	.024160
-----	-----------	--------------	---------

T.E = .024160

4710A 4710A

111	1.900000 x	15.643441 =	29.722538
509	.005305 x	604.000369 =	3.204222
613	1.000000 x	6.449699 =	6.449699
509	.000361 x	604.000369 =	.218044
112	2.400000 x	17.205541 =	41.293298
630	.200000 x	.546949 =	.109390
112	1.200000 x	17.205541 =	20.646649

T.E = 101.643840

4710A.1 4710A.1

111	1.900000 x	15.643441 =	29.722538
614	1.000000 x	11.416883 =	11.416883
509	.000361 x	604.000369 =	.218044
630	.200000 x	.546949 =	.109390
112	2.400000 x	17.205541 =	41.293298
509	.005305 x	604.000369 =	3.204222
112	1.200000 x	17.205541 =	20.646649

T.E = 106.611024

4710B 4710B

111	1.900000 x	15.643441 =	29.722538
509	.000361 x	604.000369 =	.218044
509	.005305 x	604.000369 =	3.204222
630	.200000 x	.546949 =	.109390
622	1.000000 x	15.340623 =	15.340623
112	2.400000 x	17.205541 =	41.293298
112	1.200000 x	17.205541 =	20.646649

T.E = 110.534764

4720A 4720A

111	1.900000 x	15.643441 =	29.722538
4522	140.000000 x	.029596 =	4.143440
4512	1.000000 x	1.811360 =	1.811360
671	20.000000 x	1.004869 =	20.097380
112	2.400000 x	17.205541 =	41.293298
112	2.000000 x	17.205541 =	34.411082
4511B	1.000000 x	77.872129 =	77.872129
111	1.000000 x	15.643441 =	15.643441

T.E = 224.994668

4720A.1 4720A.1

111	1.900000 x	15.643441 =	29.722538
111	1.000000 x	15.643441 =	15.643441
4522	140.000000 x	.029596 =	4.143440
4512	1.000000 x	1.811360 =	1.811360
4511B.1	1.000000 x	24.349129 =	24.349129
671.1	20.000000 x	.677784 =	13.555680
112	2.000000 x	17.205541 =	34.411082
112	2.400000 x	17.205541 =	41.293298

T.E = 164.929968

4800 4800

325	1.000000 x	2.780000 =	2.780000
112	.010000 x	17.205541 =	.172055

T.E = 2.952055